Resource No: 151

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 301 W. Yandell Dr., El Paso, Texas 79902

Latitude: 31.764156°/Longitude: -106.490091°

Function/Sub-function: Commerce/Business (Currently, Commerce/Business)

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a former gas station with influences from the Ranch architectural style.

Review of TxDOT's A Field Guide to Gas Stations in Texas indicates that this building may have been built as a Shell gas station, based on its overall design. It has a front-gable roof

with a side-gable extension and a front-gable canopy extending from the primary (southeast) elevation and supported by metal posts founded in the former gas pump island. This resource is clad in stucco and brick. This resource has metal full height windows at the primary entrance. The garage bays have been infilled with stucco and metal sash windows. The gas pumps and sign associated with the former function as a gas station are no longer extant. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.

Resource No: 152

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 813 N. Kansas St., El Paso, Texas 79902

Latitude: 31.764653°/Longitude: -106.489913°

Function/Sub-function: Funerary/Mortuary (Currently, Education/Campus Office)

Construction Date: 1924

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments:

This resource is a three-story brick building with influences from the Italian Renaissance architectural style. It was originally the Peak-Hagedon Funeral Home, which fronted Montana Street, and it is currently used as part of the IDEA Public School system. It has a flat roof with a wide overhanging visor roof on the northeast elevation. The visor roof is clad in clay tile and has wide overhanging wooden eaves supported by decorative wooden brackets and exposed wooden rafters and beams. On the northeast elevation, the resource is accessed from an arched entry at the southwest corner and a wooden paneled, double door centered on the elevation. The centered entryway is recessed into an archway accentuated with brick quoins and situated underneath a Juliette balcony. There is also a non-historic-age addition on the southwest elevation that is accentuated by a four-story tall, open frame metal box with a sign at the top. This resource has vinyl sash windows, with those on the first level having stone lintels or brick arched hoods, as well as new window openings on the northeast elevation. The original front facade of the building along Montana has window and door openings that have been infilled. The addition at the rear is clad in stucco and has a flat roof with parapet and stucco coping. The windows on the addition are vinyl sash. This building has undergone numerous changes since its construction and no longer retains its historic integrity of materials, design, workmanship, feeling, and association, and it is recommended not NRHP eligible.



Facing southeast, showing the original front entrance to the building on Montana Ave.



Facing southwest.



Facing west, note the large addition on the left.

Resource No: 153

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 810 N. Kansas St., El Paso, Texas 79902

Latitude: 31.764885°/Longitude: -106.489362°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1975

NRHP Eligibility: Not contributing to the amended area of the Rio Grande Avenue Historic District; Not

eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, one-part commercial building with a rectangular plan and a

flat roof with brick parapet. It is clad in brick and has an attached, partial-width, flat roof porch supported by brick columns. The resource has large metal picture windows that flank each side of the metal glazed entry door. The windows are covered by security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing north.

Resource No: 154

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 415 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.764851°/Longitude: -106.488871°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1920

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a three-story, Spanish Colonial Revival-style apartment building. This

resource has a rectangular plan and a flat roof with a stucco parapet. The parapet has a tiled coping with an arched architectural frieze over the end bays of each elevation to lend the appearance of towers on the building. A tiled visor roof is between the end bays on all but the northwest elevation. This resource is clad in stucco and has stucco molded quoins flanking each side of the end bays on the second and third level of all but the northwest elevation. This resource is accessed from the primary (southeast) elevation through a recessed entry situated underneath an attached stucco awning with a tiled half-hipped roof. This resource has metal sash windows. ICF recommends this resource is contributing

to the NRHP-eligible amended area of the Rio Grande Avenue Historic District.



Facing west.

Resource No: 155

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 412 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.764486°/Longitude: -106.488699°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, one-part commercial building a rectangular form and a flat

roof with a stucco parapet. It is clad in a combination of brick and stucco. This resource is accessed from the primary (northwest) elevation through a double metal door centered on the elevation. This resource has metal sash windows on the primary (northwest) elevation. It has an attached ca. 2000 sheet metal-clad addition with a flat roof on the northeast elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 156

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 707 N. Campbell St., El Paso, Texas 79902

Latitude: 31.764501°/Longitude: -106.488421°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1965

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, one-part commercial building with no distinct architectural

style. It has a rectangular plan and a low-pitched front-gable roof. This resource is clad in a combination of stucco and brick. This resource is accessed from the rear (southwest) elevation through a metal glazed doubled door. It has metal sash windows on the primary (northeast) elevation. Research did not reveal that the building is associated with

important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.

Resource No: 157

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 409 E. Missouri Ave., El Paso, Texas 79901

Latitude: 31.763413°/Longitude: -106.488141°

Function/Sub-function: Domestic/Hotel

Construction Date: Ca. 1980

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a multi-story hotel with no distinct architectural style. It has a rectangular

plan and a flat roof. This resource is clad in a combination of stucco and brick. Cornices delineate each level of the building. An additional cornice between the sixth and seventh levels give the upper levels a boxed in effect. It is accessed from the primary (southeast) elevation. This resource has metal sash windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.

Resource No: 158A

El Paso County, Texas Project Location:

Downtown 10 (CSJ: 2121-02-166) Project Name and CSJ:

810 N. Campbell St., El Paso, Texas 79902 Address, Lat/Long:

Latitude: 31.765422°/Longitude: -106.488470°

Function/Sub-function: Religion/Religious Facility (The Church of St. Clement Episcopal Church)

1908 Construction Date:

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District;

Meets Criterion Consideration A, Individually NRHP-eligible under Criterion C

Integrity/Comments: This resource is a Gothic Revival and Richardsonian Romanesque-style The Church of St.

> Clement Episcopal Church clad in rusticated stone. It has a cruciform plan with cross-gable roof and towers topped with stone battlements that are attached at the corners of the primary (southwest) elevation. Between the towers, a set of concrete steps leads to a wood paneled, double door set within a cast stone Gothic arch. This resource has wood sash tracery windows set in cast stone Gothic arch openings with stone hoods. This resource features a large rose window on the primary (southwest) elevation within the gable end. A two-story educational building, which matches the church's architectural style, is attached to the church's northeast corner to extend the building to the southeast. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District, and it was previously recommended NRHP-eligible under Criteria C in the HHM 2020 Historical and Architectural Survey for the County of El

Paso. ICF maintains this eligibility recommendation.



Facing east.



Facing north.

Resource No: 158B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 810 N. Campbell St., El Paso, Texas 79902

Latitude: 31.765515°/Longitude: -106.488228°

Function/Sub-function: Religion/Religious Facility


Construction Date: Ca. 1970

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is the Whyburn-Roderick Hall associated with the St. Clement's Episcopal

Church. It has no distinct architectural style. This resource has a rectangular plan with a flat roof. It is clad in brick and has metal sash windows. This resource is accessed on the northeast elevation. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing north.

Resource No: 158C

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 810 N. Campbell St., El Paso, Texas 79902

Latitude: 31.765617°/Longitude: -106.487828°

Function/Sub-function: Religion/Religious Facility (Christian Education Complex)

Construction Date: Ca. 1980

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource, with no distinct architectural style, is an educational building associated to The Church of St. Clement Episcopal Church. It has a rectangular plan with a flat roof and

a stone parapet. This resource is clad in stone masonry and sits atop a concrete

foundation. This resource is accessed through the primary (northwest) elevation. It has full height, metal windows set in stone casings. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains

this eligibility recommendation.



Facing north.

Resource No: 159

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 500-504-510 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.764847°/Longitude: -106.488127°

Function/Sub-function: Commerce/Business (Currently, Civic/Community Outreach)

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, one-part commercial building with no distinct architectural

style. It has a rectangular plan and a flat roof. This resource is clad in a combination of brick and stucco. This resource has glass block transom windows located above a metal awning and metal sash storefront windows. Each of the three storefronts has a metal glazed door. Windows and doors are covered in metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing southeast.

Resource No: 160

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 710 N. Campbell St., El Paso, Texas 79902

Latitude: 31.764662°/Longitude: -106.487953°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a two-story, National Folk-style, single dwelling with gable-on-hip roof and

a front gable projection on the primary (southwest) elevation. It is clad in brick, and the gable end has wood shingles. There is a cornice of dentils at the eaves. This resource is accessed from the primary (southwest) elevation by a concrete accessibility ramp or a set of concrete stairs leading to an attached, partial-width, hipped roof porch with a second level balcony. This resource has metal sash windows and rusticated stone lintels. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. This resource was surveyed in the HHM 2020 *Historical and Architectural Survey for the County of El Paso*, and it was included as not eligible and not part of the nearby Rio Grande amended boundary. ICF maintains this eligibility recommendation and also recommends the

resource as not eligible for the NRHP.



Facing northeast.



Facing southeast.

Resource No: 161

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 708 N. Campbell St., El Paso County, Texas 79902

Latitude: 31.764580°/Longitude: -106.487873°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1955

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, Contemporary-style apartment with U-shape plan and a shed

roof. It is clad in a combination of brick and stucco. This resource is accessed from the primary (southwest) elevation through a gated entrance leading to a central courtyard where each unit can be accessed through a vinyl door with security bars. The windows are vinyl sash windows covered with security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing north.



Facing east.

Resource No: 162

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 700 N. Campbell St., El Paso, Texas 79902

Latitude: 31.764516°/Longitude: -106.487592°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photographic documentation of this resource was partially obscured due to vegetation and

security fencing around the property. This resource is a two-story apartment with minimal influences from the Spanish Colonial Revival architectural style. This resource has an L-shape plan and a flat roof with brick parapet. It is clad in brick and has brick bracketed coping on the parapet. The resource is accessed through a recessed arcade entry with six brick arches. It has vinyl sash windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. While the building has influences of the Spanish Colonial Revival style, it post-dates the style's period of prominence (1915-1940). Furthermore, the replacement windows, and the infilled openings around them, substantially change the look of the building. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing north.



View of Resource No. 162 prior to windows being replaced (image courtesy of Google Streetview, 2022).

Resource No: 163A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 526-530-532 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.765067°/Longitude: -106.487684°

Function/Sub-function: Commerce/Business (Currently, Civic/Community Outreach)

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story, one-part commercial building with no distinct architectural

style. It has a rectangular plan with a flat roof, and it is clad in brick. This resource is accessed from the primary (northwest) elevation via recessed metal glazed doors. This resource has metal sash windows that are covered by security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing south.



Facing southeast.

Resource No: 163B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 600 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.765472°/Longitude: -106.487828°

Function/Sub-function: Commerce/Storage

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a rectangular outbuilding with a flat roof associated with the adjacent non-

historic-age gymnasium. This resource is clad in brick and has twelve-pane, metal sash windows covered by security bars. Research did not reveal that the building is associated

with important events or people identified in the historic context, and it is not

architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 164

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 620 E. Yandell Dr., El Paso, Texas 79902

Latitude: 31.765662°/Longitude: -106.486887°

Function/Sub-function: Religion/Religious Facility (The Church of St. Clement Episcopal Church Youth Activity

Center)

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is the one-story, St. Clement's Youth Activity Center with no distinct

architectural style. It has a rectangular plan and a flat roof. This resource is clad in stone. It is accessed from the primary (northwest) elevation by a double metal door. This resource has small, glass block windows that line the primary (northwest) elevation in groups of three, and on the northeast and southwest elevations in groups of four. There is a windowless, two-story tall, stucco-clad section at the southwest corner of the building. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP under Criterion A, B, or C.



Facing southeast.



Facing south.

Resource No: 165A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 710 N. Ochoa St., El Paso, Texas 79902

Latitude: 31.762248°/Longitude: -106.489334°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1900

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: Photographic documentation of this resource was partially obscured due to vegetation on

the primary (southwest) elevation. This resource is a one-story, Folk Victorian-style, single dwelling with a cross-hipped roof and front-gable dormer on the primary elevation. It has a brick ridge chimney. The house is clad in brick, and the gable end has wood siding. A set of steps leads to an attached, partial-width, hipped roof porch supported by metal posts. This resource has double-hung, wood sash windows that are covered by security bars. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility recommendation. Even though HHM recommended this resource individually eligible for the NRHP under Criterion C, there is little evidence to support its architectural distinction among the other resources in the

immediate vicinity and within the city.



Facing west.

Resource No: 165B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 710 N. Ochoa St., El Paso, Texas 79902

Latitude: 31.765819°/Longitude: -106.486124°

Function/Sub-function: Domestic/Secondary Structure (garage)

Construction Date: Ca. 1920

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a rectangular building with a shed roof and stone parapets on the side

elevations. It is clad in stone and has at least one window on the northeast elevation that is covered with security bars. This resource has two garage bays on the southeast elevation that have been boarded up with plywood. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso.

ICF maintains this eligibility recommendation.



Facing west.

Resource No: 166A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 708 Ochoa St., El Paso, Texas 79902

Latitude: 31.763413°/Longitude: -106.488141°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not NRHP-eligible under Criterion A, B, or C

Integrity/Comments: This resource is a two-story, single dwelling that has no distinct architectural style. It has

undergone multiple twentieth century alterations and additions. This resource has a rectangular plan with a combination of a side-gable and shed roof. This resource has a large, polygonal dormer on the primary (southeast) elevation with a pyramidal roof. This resource is clad in a combination of brick, wood siding, wood shingles, and vinyl siding. A set of stone steps leads to an attached, partial-width, shed-roof porch supported by wood columns set on stone plinths. A portion of the porch has been enclosed. The resource has a combination of vinyl sash windows and fixed wood sash windows. This resource has an attached garage addition to the northeast elevation. It has a shed roof, is clad in brick, and has a wooden garage door. This resource was recommended not contributing to the amended area of the Rio Grande Avenue Historic District in the 2020 *Historical and* 

Architectural Survey of the County of El Paso. ICF recommends the previous

recommendation of NRHP eligibility is maintained, and ICF recommends that the property

is not individually eligible under Criterion A, B, or C.



Facing northwest.



Facing northeast.

Resource No: 166B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 708 Ochoa St., El Paso, Texas 79902

Latitude: 31.763413°/Longitude: -106.488141°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a two-story, Mission Revival-style multiple dwelling with a flat roof and

triangular parapet. It is clad in brick. The resource is accessed from the primary (southwest) elevation through a wooden glazed door with transom window and security bars. There is a metal balcony above the primary entrance. The window type could not be identified as all windows are covered with louvered storm windows. Some first level windows also have security bars. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and Architectural Survey of the County of El Paso*. ICF maintains

this eligibility recommendation.



Facing west.

Resource No: 167

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 705 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.764516°/Longitude: -106.487592°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, single dwelling with gable-on-hip roof and front-gable

projection on the primary (southeast) elevation. This resource likely had Folk Victorian styling at one time; however, that detailing is largely non-extant. A set of tiled steps leads to the attached, partial-width, hipped roof porch supported by wood posts. This resource has vinyl sash windows. It has brick sloped chimneys on the northeast and southwest elevations. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and* 

Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing north.

Resource No: 168

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 709 Wyoming Ave., El Paso, Texas 77902

Latitude: 31.765615°/Longitude: -106.485906°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District,

Individually eligible under Criterion C

Integrity/Comments: This resource is a one-story, Folk Victorian-style dwelling with a gable-on-hip roof and front

gable projection on the primary (southeast) elevation. The resource is clad in brick and has a brick patterned frieze. The gable end has Territorial Revival details with its circular gable

vent and four keystones surrounding the vent. A set of concrete steps leads to an attached, partial-width, hipped-roof porch supported by four wooden posts and with wooden, slender, turned spindle work at the eave. This resource has double-hung, wood sash windows that are partially covered by security bars. This resource has two brick slope chimneys. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and Architectural Survey of the County of El Paso*. The HHM survey also included this resource as individually eligible under Criterion C as an unusual Folk Victorian with Territorial

Revival details. ICF also maintains both eligibility recommendations.



Facing north.

Resource No: 169

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 711 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.764898°/Longitude: -106.486248°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1900

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Queen Anne dwelling with gable-on-hip roof and conical-roof

turret on the primary (southeast) elevation. The house is clad in brick and has decorative brick patterns on the corners. A set of concrete steps leads to the attached, partial-width, shed-roof porch supported by wooden posts. This resource has vinyl sash windows with stone lintels. This resource has brick slope chimneys on the southwest and northeast elevations. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and Architectural Survey of the County of El Paso*. ICF maintains this eligibility

recommendation. Even though HHM recommended this resource individually eligible for the NRHP under Criterion C, there is little evidence to support its architectural distinction

among the other resources in the immediate vicinity and within the city.



Facing northwest.

Resource No: 170

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 717 N. Wyoming Ave., El Paso, Texas, 79902

Latitude: 31.765754°/Longitude: -106.485676°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This one-story brick building has a gable-on-hip roof with a projecting front-gable ell. A half-

circle vent and gable returns are located in the gable-end. There is a small, attached partial-width shed-roof porch with two wood turn-post columns. The primary pedestrian entrance is accessible on the southeast elevation, and it has two wood doors with a small rectangular transom light. The window openings have stone lintels and brick sills. The windows on each elevation are a combination of replaced fixed, sash, and casement windows. A review of historic aerials indicates that there is a small ca. 2000 shed-roof addition on the northwest elevation that was not visible from the public ROW. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility recommendation.



Facing west.

Resource No: 171

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 719 N. Wyoming Ave., El Paso, Texas, 79902

Latitude: 31.765828°/Longitude: -106.485568°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This house has a gable-on-hip roof and projecting front-gable ell. There is wood imbrication

in the gable-end and stone lintels above the windows. There are numerous replacement sash and casement windows on each visible elevation. The primary entrance is on the southeast elevation and accessed via an attached shed roof porch. The pedestrian door is metal with a small rectangular transom light. The entire porch has a decorative full-height metal security gate around the perimeter of the porch. A review of historic aerials indicates that there are multiple non-historic-age buildings and sheds on the northwest elevation of this parcel. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and

Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing west.

Resource No: 172

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 610 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.764898°/Longitude: -106.486248°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story auto repair building with no distinct architectural style. It has a

rectangular plan and a flat roof with attached metal awning on the primary (northwest) elevation. This resource is constructed of cinderblock. On the primary (northwest) elevation, the building has a glazed pedestrian door and six garage bays with overhead garage doors. A shed roof, corrugated metal addition to the building's southwest end adds a seventh bay that does not have an overhead door. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP under Criterion A, B, or C.



Facing south.

Resource No: 173

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 702 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.764662°/Longitude: -106.487953°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Folk Victorian dwelling with gable-on-hip roof and a front-gable

projection with eave returns on the primary (northwest) elevation. This resource is clad in a combination of stucco with stone quoins. A set of tiled steps leads to an attached, partial-width, hipped roof porch supported by stone-clad columns and the glazed panel door. This resource has vinyl sash windows. This resource has one brick slope chimney on the northeast elevation. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing southeast.

Resource No: 174A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 704 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.764847°/Longitude: -106.488127°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Folk Victorian-style dwelling with a gable-on-hip roof and a

front-gable projection. It is clad in stucco, and the gable end is clad in wood shingles. The house has an attached, partial-width, hipped roof porch supported by wooden posts and with wooden, slender, spindle work at the eave. This resource has vinyl sash windows. It has brick slope chimneys on the southeast, southwest, and northeast elevations. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and Architectural* 

Survey of the County of El Paso. ICF maintains this eligibility recommendation.



Facing southeast.

Resource No: 174B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 704 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.765045°/Longitude: -106.485615°

Function/Sub-function: Domestic/Secondary Structure

Ca. 1940 Construction Date:

NRHP Eligibility: Not contributing to the NRHP-eligible amendment area of the Rio Grande Avenue Historic

District; Not individually NRHP-eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a shed roof. According to the 1948 Sanborn maps, it was

originally built as a 3-car garage and is constructed with concrete block that has been covered in stucco. Since the resource was originally a 3-car garage, the south-facing side of the building has changed significantly with the solid wall and three sets of paired windows replacing the former garage doors. ICF recommends this resource is not

contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

and that it is not individually NRHP-eligible under Criterion A, B, or C.



Facing north/northwest.

Resource No: 175

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 706 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.765067°/Longitude: -106.487684°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Folk Victorian dwelling with singular dwelling with a hipped

roof and a front-gable projection. The resource is clad in stucco, and the gable end is clad in wood shingles. A set of concrete steps leads to the attached, partial-width, hipped roof porch supported by wooden posts. This resource has vinyl sash windows. It has two brick slope chimneys on the southwest elevation. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 *Historical and Architectural Survey of the County of El Paso*. ICF maintains

this eligibility recommendation.



Facing southeast.

Resource No: 176

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 708 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.765422°/Longitude: -106.488470°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Folk Victorian dwelling with hipped roof and front-gable

projection on the primary (northeast) elevation. It is clad in brick, and the gable end is clad in diamond-shaped wooden shingles and has a diamond-shaped gable vent. It has an attached, partial-width, hipped roof porch supported by wood posts. The resource has vinyl sash windows. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing southwest.

Resource No: 177

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 710 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.765662°/Longitude: -106.486887°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This resource is a one-story, Folk Victorian dwelling with hipped roof and front-gable

projection on the primary (northwest) elevation. The house is clad in brick, and the gable end is clad in wood shingles with a Palladian-style vent. A set of concrete steps leads to the integrated, partial-width porch supported by a metal post. The resource has vinyl sash windows with stone lintels. This resource has one brick sloped chimney at the rear (southeast) elevation. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in HHM's 2020 Historical and Architectural Survey of the County of El Paso. ICF maintains this eligibility

recommendation.



Facing southeast.

Resource No: 178

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 619 N. Virginia St., El Paso, Texas, 79902

Latitude: 31.765509°/Longitude: -106.485372°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a gable-on-hip roof with a front-gable projection centered on

house was built with Folk Victorian detailing, although the majority of that detailing is not extant. There is one brick chimney on the northwest elevation that has been closed off. The building has sash and fixed windows on each elevation, and the original window openings had to be modified to fit the non-historic-age replacements. The primary (northeast) elevation has a replacement pedestrian door and picture window. The primary entrance is beneath a ca. 2000 shed roof, partial-width porch addition that is supported by multiple wood posts. The porch addition connects to a ca. 2000 flat roof, cinderblock addition on the northeast elevation. This addition has two pedestrian doors and a small sash window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

the northeast elevation. There is wood imbrication in the gable-end indicating that the

recommends the resource as not eligible for the NRHP.



Facing southwest



Facing south

Resource No: 179

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 615 N. Virginia St., El Paso, Texas, 79902

Latitude: 31.765410°/Longitude: -106.485334°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story house has a gable-on-hip roof with a centered front-gable projection on the

primary (northeast) elevation with diamond-shaped wood imbrication in the gable-end. The building is constructed with brick. There is an attached, half-hip porch on the primary elevation that is supported by wood posts with small brackets. Centered beneath the porch is a non-historic-age metal pedestrian door flanked by two non-historic-age large fixed windows. The visible windows on the southeastern elevation have been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southwest



Facing west

Resource No: 180

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 611 N. Virginia St., El Paso, Texas, 79902

Latitude: 31.765321°/Longitude: -106.485232°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1900

NRHP Eligibility: Contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District

Integrity/Comments: This one-story Folk Victorian building has a cross-hip roof with a centered gable dormer

with wood shingles on the northeast and southwest elevations. The house has small repeating brackets under the eaves, and there are three visible brick chimneys on the roof line. This residence was originally constructed with brick but was covered with stucco in ca. 2015. The house has arched window openings with brick header sills. The entirety of the building has replacement, non-historic-age sash windows. Given that this resource is used as a multiple dwelling, there are several entrances on each elevation, all of which has a wood pedestrian door covered by a metal security door. Some of the entrances are accessed via an attached, partial-width porch with replacement wood posts, replacement brackets, and replacement railings. ICF recommends this resource is contributing to the NRHP-eligible amended area of the Rio Grande Avenue Historic District as outlined in

HHM's 2020 Historical and Architectural Survey of the County of El Paso.



Facing northwest



Facing west

Resource No: 181

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 420 N. Campbell St., El Paso, Texas, 79901

Latitude: 31.763948°/Longitude: -106.484935°

Function/Sub-function: Transportation/Rail-related (Currently, Recreation/Event Space)

Construction Date: 1903

NRHP Eligibility: Eligible under Criteria A and C

Integrity/Comments: The El Paso & Southwestern Railroad Depot exhibits the Italianate architectural style. This

resource has a rectangular form and a hipped roof with large single and paired brackets under the wide eaves. This resource is clad in brick with stone rounded arches and segmented arches above the windows and doors on the first level. There is a stone belt course between the first and second stories. The second-story window surrounds are accentuated with brick detailing. This resource has multiple access points on the southwest and southeast elevations. The consulting parties noted this building as a resource of concern, and it was previously recommended NRHP-eligible as part of HHM's 2020 *Historical and Architectural Survey of the County of El Paso*. ICF maintains this

NRHP eligibility recommendation under Criteria A and C.



Facing northeast



Facing north



Facing north

Resource No: 182

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 800 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.765648°/Longitude: -106.484628°

Function/Sub-function: Commerce/Business

Construction Date: ca. 1980

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story resource is a commercial building. This resource has a combination of a flat

roof at the primary (southwest) elevation and a side-gabled roof. This resource is clad in a combination of stucco and cinderblock. This resource has multiple fixed windows and multiple points of access from the primary (southwest) elevation through a full width, flat-roof porch. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommende the recourse of not eligible for the NDLD

recommends the resource as not eligible for the NRHP.



Facing northeast



Facing northeast



Facing east



Facing north

Resource No: 183A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 810 Wyoming Ave., El Paso, Texas, 79902

Latitude: 31.765941°/Longitude: -106.484650°

Function/Sub-function: Domestic/Multiple Dwelling


Construction Date: ca. 1900

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This National Folk resource is a two-story brick building with a hip roof and a hip dormer on

the primary (northwest) elevation. This resource is accessed from the primary (northwest) elevation by a set of concrete steps leading to a shallow, partial-width, attached porch situated underneath a hip roof supported by square columns on brick pedestals. This resource's front façade has aluminum sash windows with stone lintels, and the side elevations have brick lintels and sills. There is a brick belt course between the first and second floors with a simple metal sign that reads "Young Mens Christian Association." The YMCA appears to have an office at this location since the 2010s; however, the organization does not own the building and no lease was announced in the newspaper or recorded with the county. Research indicates that this building was divided into apartments and owned by private individuals or companies. In 2021, a consulting party identified this as a property of note with information related to McMath Printing. *The El Paso Times* indicates that McMath Printing was located at 520 W. San Antonio Street in

1926, and later at the corner of Wyoming and Cotton. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not NRHP eligible.



## Facing southeast



Facing south

Resource No: 183B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 810 Wyoming Ave., El Paso, Texas, 79902

Latitude: 31.766085°/Longitude: -106.484449°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1900

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a two-story brick building with rectangular form and a flat roof with a brick

parapet. This resource is accessed from the primary (northwest) elevation by a set of masonry steps and an accessibility ramp leading to a two-story, partial width, attached porch situated underneath a dropped flat roof and supported by brick columns. The second-store porch has a brick knee wall with recessed panel. This resource has replacement doors and replacement vinyl sash windows. The window openings have stone lintels and sills. This resource has one brick exterior chimney on the northeast elevation and two brick exterior chimneys on the southwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast



Facing east



Facing southwest

Resource No: 184

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 613 N. Saint Vrain St., El Paso, Texas, 79902

Latitude: 31.765890°/Longitude: -106.484463°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is a one-story brick building with a gable-on-hip roof with a front-gable

projecting ell on the primary (northeast) elevation. This building may have originally had Folk Victorian detailing, but the detailing is not extant. This resource is accessed from the primary (northeast) elevation by a set of concrete steps leading to a partial width, attached porch situated underneath a shed roof supported by simple wooden posts. This resource has wooden sash windows, and arched brick header window openings. This resource has three brick sloped chimneys on the southeast elevation and two brick sloped chimneys on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally



Facing southwest



Facing west

Resource No: 185

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 825 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.765522°/Longitude: -106.484267°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1965

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story resource has a flat roof. The lower level is constructed with cinderblock and

has one metal pedestrian door and a large picture window covered by metal security bars on the southeast elevation. A review of historic aerials indicates that the second level was likely added in ca. 1980. The addition has a shed roof, aluminum siding, and several aluminum sliding windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally



Facing northeast.



Facing north (image courtesy of Google Earth, 2022).

Resource No: 186

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 605 Ange St., El Paso, Texas 79902

Latitude: 31.766307°/Longitude: -106.483389°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of the primary (southeast) elevation was limited due to a large

cinderblock wall. This building has a hip roof and is clad in stucco. There is a small, attached, partial-width shed-roof porch on the southeast elevation that is supported by two decorative metal posts. At the time of field investigations, the entire porch had a full-height metal gate. All visible windows have been replaced, and many of the original window openings have been modified or infilled to fit the replacements. The rear porch has been infilled. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing north.



Facing south, note the primary entrance and front porch is to the far left.

Resource No: 187

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 610 Ange St., El Paso, Texas 79902

Latitude: 31.766655°/Longitude: -106.483147°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a pyramidal roof with a projecting front-gable that is clad in

stucco. All visible windows are non-historic-age replacements, and the original window openings have been modified or infilled to fit the replacements. The primary elevation of this resource was historically the southwest elevation beneath the full-height front-gable entry. However, there is a non-historic-age shed roof addition on the southwest elevation that forced the reorientation of the primary entrance to the rear (northeast) elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing north.

Resource No: 188

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1008 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.766871°/Longitude: -106.483068°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story, rectangular building has a flat roof with parapet on the northwest elevation.

The building is constructed with cinderblock and clad in stucco and a stone veneer on the bulkhead of the northwest elevation. There is a full-width, flat metal awning on the primary (northwest) elevation. The northwest elevation also has two replacement metal pedestrian doors, each with a transom light. Between the two pedestrian doors are two sets of large, replacement fixed windows covered by fixed metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing south.

Resource No: 189A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1012 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.766983°/Longitude: -106.482960°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story, square building has a flat roof. The building was originally constructed with

brick (apparent on the southeast elevation), but the northwest, southwest, and northeast elevations have been covered with stucco. There is horizontal banding on the lower and middle third of the building. The primary entrance is centered on the northwestern elevation beneath an enclosed, one-story front-gable entry with a rounded tile roof. All visible windows have been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 189B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1012 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.766868°/Longitude: -106.482825°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a gable roof and wood paneled siding. There were no visible

pedestrian doors, but for a small metal door on the presumed utility closet. The resource has non-historic-age replacement sash and fixed windows, and some have been covered with metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally



Facing north (image courtesy of Google Earth, 2022).

Resource No: 190

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1020 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767121°/Longitude: -106.482763°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian brick house has a cascading hip roof with a projecting front-gable ell on

the primary (northwest) elevation. The front-gable ell has an ocular window and gable returns in the gable-end. Additionally, there is some decorative brick work on the façade of the ell, including a brick header arch over the window and an angled header and modest banding. The primary entrance has a wood pedestrian door with transom light located beneath an attached porch. The porch is supported by wood turned posts and a portion of the porch opening has been covered with lattice. All visible windows have been replaced, and many of the original window openings on the southwest elevation have been modified to fit the replacements. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally



Facing southeast.



Facing south (image courtesy of Google Streetview, 2022).

Resource No: 191

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1022 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767107°/Longitude: -106.482593°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1955

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large, rectangular commercial building has a flat roof with an angled accent wall on

the building's north corner. It is constructed with cinderblock that has been covered with stucco and there is a brick veneer on the lower third of the primary (northwest) elevation.

The primary elevation has one metal-frame glass pedestrian door surrounded by

rectangular transom and sidelights. The primary elevation also has large, fixed windows. This type of commercial building is common in the area. The windows and door are sheltered by a full-width metal awning. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 192A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1024 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767240°/Longitude: -106.482486°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: The building has a gable-on-hip roof with a projecting front-gable on the northwest

elevation, with a small window and decorative wood imbrication in the gable-end. The majority of the building is clad in stucco, and the window openings are arched and have stone sills. The primary (northwest) elevation has a ca. 1950 wrap-around porch supported by several decorative metal posts and brackets. There are two wood pedestrian doors, and both have a small transom light. All visible windows are non-historic-age replacements. A review of historic aerials indicates that there is a large ca. 2000 addition on the southeast elevation of this building. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally



Facing south.

Resource No: 192B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1024 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767126°/Longitude: -106.482396°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1900

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story brick building has a flat roof with decorative brick corbels at the roofline.

The window openings on the southeast elevation have arched brick header lintels. At the time of field investigations, all visible windows had been covered with plywood. There is a single-bay garage on the southeast elevation covered by a metal gate. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing north (image courtesy of Google Earth, 2022).

Resource No: 193A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1030 E. Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767370°/Longitude: -106.482398°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story brick apartment building has a flat roof, three brick chimneys, and brick

coping at the roofline. There is a full width, attached two-story porch supported by brick columns. There are brick knee walls with recessed panels on the first and second floor porches and a decorative metal railing on the second-story porch. Between the floors are a series of stucco panels with recessed insets. The non-historic-age pedestrian doors are accessible from the primary (northwest) elevation. There are multiple sash and fixed windows on each elevation, and all have been replaced. Each window and door have a stone lintel and sill. There is a full-width, two-story shed roof addition on the southeast elevation that is clad in stucco. The building materials are incongruent with the rest of the resource. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing southeast.



Red arrow indicates ca. 1950 addition, facing south.

Resource No: 193B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 609 Octavia St., El Paso, Texas 79902

Latitude: 31.767207°/Longitude: -106.482243°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story residence has a hip roof and centered hip-roof dormer with covered windows

on the northeast elevation. There are four brick chimneys, and the building is constructed with brick. The primary (northeast) elevation has a two-story attached porch. The lower level has decorative metal security bars along the porch openings. The visible wood pedestrian doors have transom lights. The window openings have brick header sills, and all visible sash windows have been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing west.

Resource No: 193C

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 609 Octavia St., El Paso, Texas 79902

Latitude: 31.767290°/Longitude: -106.482261°

Function/Sub-function: Domestic/Secondary Structure (garage)

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story garage has a flat roof and is constructed with brick. There are two single-

bay, hinged doors on the primary (northeast) elevation located beneath a lintel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource

as not eligible for the NRHP.



Facing southwest (image courtesy of Google Streetview, 2022).

Resource No: 194

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 606 Ange St., El Paso, Texas 79902

Latitude: 31.766508°/Longitude: -106.483053°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman bungalow has a cross-hip-on-gable house has an exposed brick chimney

and wood shingles and wood brackets in the visible gable-ends. The residence retains many of the original lintels and sills, as well as the historic-age wood sash windows on the northwest elevation. The primary (southwest elevation has a full-width, integrated porch supported by two battered brick columns and there is a brick knee wall around the perimeter of the porch. Beneath the porch is a replacement wood door, one non-historicage fixed window, and one replacement sash window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing east.

Resource No: 195

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1001 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766441°/Longitude: -106.482964°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1940

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story brick commercial building has a hip roof with a raised stepped brick parapet

that has a brick square panel detail on the southwest elevation. The southwest elevation has multiple infilled and replacement windows, and a single-bay garage door that has been converted to a pedestrian entrance. There is a small side-gable carport addition on the southeast elevation supported by two metal posts. Beneath the carport is the primary pedestrian entrance, which is a door flanked by two wood sash windows. The southeast elevation also has a metal pedestrian door, single-bay garage door, and multiple infilled windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing north.



Facing west.

Resource No: 196

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1009 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766603°/Longitude: -106.482722°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1960

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large rectangular brick building has a flat roof and tall corrugated metal parapet on

the southeast elevation. All of the fixed windows on the primary (southwest) elevation have been replaced, and the original openings have been infilled to fit the replacements. There is one metal-frame glass door on the southeast elevation, and several replacement sash windows on the southwest elevation that are covered by metal security bars. There is a large non-historic-age premanufactured shed at the rear of this parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing north.

Resource No: 197A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1027 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766866°/Longitude: -106.482125°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1930

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is one of many resources on the property, and partially obscured by security

fencing and difficult to photograph due to its proximity to adjacent resources. This building has a flat roof with a raised parapet. The building is clad in stucco. There is a small shedroof overhang with rounded tiles supported by two non-historic-age classical columns. The set of double doors are wood, and they are flanked by two non-historic-age fixed windows that are covered by metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing west.



Aerial view of the property (image courtesy of Google Earth, 2022).

Resource No: 197B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1021 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766736°/Longitude: -106.482323°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1930

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This split-level resource has a flat roof with raised corners on each elevation and

interlocking rounded tiles outlining the primary (southeast) elevation's roofline. The building was constructed with brick and has been coated with stucco. This resource has multiple storefronts, each with a metal-frame glass door and fixed, replacement windows beneath decorative metal security bars. A review of historic aerials indicates that this building has had numerous alterations and additions beginning in ca. 1980, which included combining several smaller buildings under one roofline. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing west.



Facing north.

Resource No: 197C

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1025 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766846°/Longitude: -106.482297°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this resource was limited as it is one of many resources on the

property, and it was obscured by fencing. This building has a parallel gable, corrugated metal roof and the building is clad in stucco. Only one metal-frame glass pedestrian door on the southeast elevation was visible at the time of field investigations. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Red arrow indicates the location of 197C, facing northwest.



Facing northwest.



Aerial view of Resource No. 197C (image courtesy of Google Earth, 2022).

Resource No: 198

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 605 Octavia St., El Paso, Texas 79902

Latitude: 31.767105°/Longitude: -106.482152°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square, two-story apartment building has a hip roof and is constructed with brick. The

primary (northeast) elevation has a metal door beneath a hip overhang, supported by two wood brackets. All windows on the visible elevations are replacement sash windows with stone lintels and sills. There is a ca. 2000 full height, shed roof addition clad in stucco on the southwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing southwest.



Facing south.

Resource No: 199

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1029 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.766941°/Longitude: -106.482030°

Function/Sub-function: Commerce/Business (Currently, Vacant/Not in Use)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story building has a flat roof with brick coping near the roofline. The building is

constructed with brick, although some elevations have been covered with stucco. The primary door is located on the southeast corner of the building, and the main door is a wood with two small sidelights, all of which are covered with metal security bars. There are numerous pedestrian doors on the southeast and northeast elevations. The windows on the second story are four-over-four arched sash windows, and many panes were missing at the time of field investigations. The first story has several infilled windows and the extant windows have been covered with plywood. In the 1920s, El Paso city directories indicate that this building was the Texas Grocery and Market. In 1945, the grocery was purchased by Reginald Ernest Ruebush and became Ruebush's Grocery and Market. It is unclear how long the property has been vacant. Research did not reveal that the building is associated

with important events or people identified in the historic context, and it is not

architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing west.



Facing southwest.

Resource No: 200A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 610 Octavia St., El Paso, Texas 79902

Latitude: 31.767540°/Longitude: -106.482133°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman bungalow has a front-gable roof with wood shingles, a covered window,

chimneys. It was originally constructed with brick and has been covered with stucco. The primary (northwest) elevation has a full-width incorporated porch supported by two cylindrical poles and two square columns. There is a modestly decorative knee wall around the perimeter of the porch. The primary pedestrian door is wood. All visible sash and fixed windows have been replaced, and one window on the porch has been replaced with a second pedestrian door. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

and wood brackets and wood shingles in the gable-end. The resource has four brick

significant. ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 200B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 610 Octavia St., El Paso, Texas 79902

Latitude: 31.767619°/Longitude: -106.481978°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square brick apartment building has a flat roof with a plain brick coping at the roofline

and a recessed paneled parapet. The second level has a small, centered balconette with a simple metal railing and wood door with small transom lights. Both levels of this resource have wood-frame sash windows, and many of the windows have been replaced. The window openings have stone sills and brick header lintels. The windows on both levels of the primary (southwest) elevation have a steeply pitched shed roof with asphalt shingles supported by wood brackets. The primary entrance is recessed and has a wood door with small sidelights. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing north.

Resource No: 201

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1104 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767619°/Longitude: -106.481978°

Function/Sub-function: Domestic/Single Dwelling (Currently, Education/Daycare)

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: The historic-age portion of this resource has a side-gable roof with a gable dormer.

Between ca. 1965 and ca. 1975, a large addition was constructed around the resource, completely obscuring the original dwelling. The false front has a large, raised parapet. The primary (northwest) elevation has two metal pedestrian doors, and two sets of large, fixed windows. It is constructed with stucco. Between ca. 1965 and ca. 1975, a large, shed roof, stucco addition was added to the rear (southeast) elevation. No portion of the original dwelling is visible. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east.



Aerial view of Resource No. 201. The red arrow indicates the only visible portion of the former dwelling (image courtesy of Google Earth, 2022).

Resource No: 202A

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1106, 1108, 1110 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767682°/Longitude: -106.481896°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1930

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource was historically a single dwelling, but that is only apparent from the existing

roofline visible in aerial photography. Between ca. 1965 and ca. 1975, the building was entirely surrounded with a cinderblock structure that has a stucco parapet with a

geometric design on the primary (northwest) elevation. The building has a full-width metal awning supported by suspension cables. Until ca. 2010, the primary façade had three store fronts with large fixed windows. Those storefronts have been replaced with three small apartments, each with a wood door and single sliding window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing southeast.



Facing south.



Aerial view of Resource No. 202A. The red arrow indicates the only visible portion of the former dwelling (image courtesy of Google Earth, 2022).

Resource No: 202B

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1106, 1108, 1110 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767530°/Longitude: -106.481716°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This small building has a flat roof with a raised parapet on the southwest and northeast

elevation. The resource is clad in stucco. There are three small sash windows on the southeast elevation that are covered by fixed metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing north (image courtesy of Google Earth, 2022).

Resource No: 203

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1112 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767741°/Longitude: -106.481773°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource has a front-gable roof and one visible brick chimney. The resource is

constructed with brick, wood panels, and stucco. The visible windows are replacement sash and fixed windows. There is a large ca. 2000 addition on the primary elevation that has a flat roof and stucco siding. There are fixed windows visible in the addition. This addition has altered the entrance to this resource and reoriented it to the northwest corner of the building. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 204A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1116 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767825°/Longitude: -106.481654°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1955

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Ranch-style house has a side-gable roof with plywood in the gable-end, and the

resource is constructed with brick. The primary pedestrian door is on the northwest elevation, and the wood door and all visible windows are non-historic-age replacements. A review of Google Streetview imagery indicates that a porch on the southeast elevation has been infilled. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 204B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1116 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767686°/Longitude: -106.481507°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1955

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a shed roof with parapet on the northwest elevation. The

building is clad in stucco. There are multiple replacement sash windows on the resource covered by metal security bars on the southeast elevation. One window and one door have been infilled. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing north (image courtesy of Google Earth, 2022).

Resource No: 205

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1120 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.767946°/Longitude: -106.481408°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This brick house has a gable-on-hip roof and a small front-gable roof over the front

entrance. This house likely had Folk Victorian details although they are no longer extant. The primary (northwest) elevation has a full-width porch supported by several metal posts. There is a decorative metal railing around the perimeter of the porch. The primary wood pedestrian door has a metal security door, and it is flanked by non-historic-age windows. A review of historic aerials indicates that this building has a ca. 2000 shed roof addition on the southeast elevation that is incongruent in building materials compared to the rest of the residence. The parcel also contains a non-historic-age carport and shed. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 206

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 611 Noble Street, El Paso, Texas 79902

Latitude: 31.767957°/Longitude: -106.481106°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This house has a front-gable roof with plywood in the gable-end, and the resource is

constructed with brick. This house likely had Folk Victorian details although they are no longer extant. The primary (southeast) elevation has a sheltered entrance supported by one decorative metal post. There are two wood pedestrian doors, and both transom lights had been covered. All visible sash windows have been replaced and some of the window openings have either been completely or partially infilled, and most windows have a stone lintel and brick header sill. There is one arched window opening on the primary elevation with a hood mold that does not appear to be original. Several doors and windows have been infilled on the southeastern elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing west.

Resource No: 207

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1121 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.767486°/Longitude: -106.481166°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: This split-level building has a flat roof and is constructed with cinderblock and clad in

stucco with masonry and brick veneer. The two-story portion of this building is located on the northwest elevation and has several pairs of small, fixed windows. The primary (southeast) elevation has one metal pedestrian door, two glass block windows, and one large picture window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing north (image courtesy of Google Earth, 2022).

Resource No: 208

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1123 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.767552°/Longitude: -106.481044°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story duplex has a front-gable roof with a Mission-inspired masonry façade and

parapet on the primary (southeast) elevation. The roofline is punctuated with small shedroof covered rounded tiles on either side of the rounded raised center parapet. The building appears to have a masonry veneer. The primary elevation has two metal

pedestrian doors, and two replacement sash windows, all of which have lintels. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource

as not eligible for the NRHP.



Facing northwest.



Facing north.

Resource No: 209

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1127 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.767700°/Longitude: -106.481011°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large, rectangular brick apartment building has a front-gable roof with repeating half-

hip bay windows along the building's southwest and northeast elevations. There is vinyl siding in the gable-end. Access to all apartments is through the primary (southeast) elevation. The main entrance is a metal-frame glass door with sidelights. Each window on each elevation of the building has a stone lintel and is a replacement sash window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends



Facing northwest.



Facing north, note the series of the bay windows along the side elevation (on left).

Resource No: 210

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 607 Noble Street, El Paso, Texas 79902

Latitude: 31.767841°/Longitude: -106.480918°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This house has a gable roof with a cross-gable addition. While the house appears to have

been built in the Craftsman style, but only wood shingles and extended purlins in the gable-end are extant. The building is constructed with brick that has been covered with stucco. projecting front-gable attached garage addition. The partial-width porch has been enclosed with both stucco and non-historic-age windows located beneath fabric awnings. A review of historic aerials indicates there is a large, flat-roof addition on the southeast elevation that has stucco siding. Research did not reveal that the building is associated

with important events or people identified in the historic context, and it is not

architecturally significant.



Facing southwest.



Facing west.

Resource No: 211

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 612 Noble Street, El Paso, Texas 79902

Latitude: 31.768194°/Longitude: -106.480737°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920


NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a hip roof with projecting front-gable attached garage addition. The

building is constructed with brick. The primary (southwest) elevation has an integrated porch supported by wood columns with arched openings. The arched openings are covered with decorative metal gates. The single-bay garage addition has been infilled to create additional living space, and now has one metal pedestrian door and sash window. All visible windows are replacement sash windows that are covered by metal security bars. There is a small, shed roof addition connected to the garage that is constructed with wood. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends



Facing east.



Facing northeast.

Resource No: 212A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1206 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768376°/Longitude: -106.480712°

Function/Sub-function: Domestic/Single Dwelling (Currently, Domestic/Multiple Dwelling)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian one-story building has a cascading hip roof with projecting front-gable

ell on the northwest elevation. There is decorative wood imbrication in the gable-end, and there are four visible brick chimneys. It was originally constructed with brick but has been clad with stucco on most elevations. The primary (northwest) façade has been significantly altered to accommodate the transition from a single dwelling to a multiple dwelling. One window has been infilled and replaced with a metal pedestrian door with transom light. Another pedestrian door is located beneath a small, shed roof supported by one metal pole. There is a large ca. 1980 shed roof addition with a Mission-inspired stucco parapet, and it has a modified window opening with non-historic-age windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast.

Resource No: 212B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1206 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768265°/Longitude: -106.480566°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a flat roof with masonry parapet on the northeast and

southwest elevations. The building is constructed with cinderblock, masonry, and wood. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends



Facing north.

Resource No: 213A

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1208 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768441°/Longitude: -106.480588°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian building has a hip roof with multiple projecting gable additions. The

building is constructed with brick, and a majority of the additions are clad in stucco or constructed with wood. A review of historic aerials indicates that the additions likely began in ca. 1980 and continued into the 2000s. The additions include a small gable wood addition on the second level that is accessible by an added exterior stairway; a wraparound shed roof porch supported by many metal posts, a first-level addition on the northwest and northeast elevations; reorientation of the primary entrance, replacement and infilled windows, and the addition of several pedestrian entrances. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing east.

Resource No: 213B

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1208 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768339°/Longitude: -106.480483°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this building was limited due to a large privacy wall. This one-story

secondary house on the property has a flat roof with attached shed-roof porch. The building is clad in stucco, and there is one pedestrian door flanked by two windows on the primary (southwest) elevation. Research did not reveal that the building is associated with

important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing north.

Resource No: 214

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1212 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768537°/Longitude: -106.480499°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This house has a hip roof with hip-roof dormer centered on the primary (northwest)

elevation with rounded and latched tiles (likely not original). The building is constructed with brick, and portions have been covered with stucco. There is a full-width, integrated porch on the primary elevation supported by decorative and simple metal posts. The primary pedestrian door is a wood door and is recessed beneath the porch. All visible windows are non-historic-age replacements, and many have been covered by metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing east.

Resource No: 215

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1214 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768595°/Longitude: -106.480436°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This National Folk house constructed has a hip roof with a centered hip-roof dormer on the primary (northwest) elevation. The resource has two visible brick chimneys. This building is

constructed with brick. The primary elevation has an integrated, full-width porch supported by three columns. The primary pedestrian entrance is recessed and has a glass door with transom light. All visible windows are replacement sash windows. At the time of field investigations, two of the vents or windows on the dormer had been covered with plywood. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends



Facing southeast.



Facing south.

Resource No: 216

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1216, 1218 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768631°/Longitude: -106.480364°

Function/Sub-function: Domestic/Single Dwelling (Currently, Domestic/Multiple Dwelling)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian building has a gable-on-hip roof. It was originally constructed with brick

but has been covered with stucco. There is an integrated, partial-width porch on the northwest elevation that is supported by two wood turn-posts, and the porch has a full-height metal gate around the perimeter. There is one visible replacement sash window on the northwest addition. A review of historic aerials indicates that there is a large ca. 1990 addition on the northeast and southeast elevations. The addition has a flat roof, parapet, one pedestrian door on the northwest elevation, and access to multiple apartments on the southeast elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east

Resource No: 217A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1220 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768720°/Longitude: -106.480225°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a gable-on-hip with cascading hip roof. This resource is constructed with

brick, and some sections have been replaced or covered with board and batten siding. The only visible window on the northwest elevation has been replaced and has metal security bars. The building has a large ca. 2000 garage addition on the northwest elevation that caused a change in the front elevation's fenestration. The garage addition is supported by two square, brick columns and the entrance to the residence is covered by a metal gate. Very few details of the historic-age portion of this residence were apparent due to the large addition. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing south/southeast.

Resource No: 217B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1220 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768568°/Longitude: -106.480128°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: View of this shed was blocked by a rock wall. This shed has a shed roof and is constructed

with cinderblock. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. It is also not original to the property. ICF recommends the resource as not eligible for the

NRHP.



Facing northwest.

Resource No: 218

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1228 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768755°/Longitude: -106.480065°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1965

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: This two-story commercial building has a flat roof and is constructed with cinderblock and

clad in stucco and brick. A review of Google Streetview imagery indicates that the lower store front has been significantly altered. The large storefront windows have been removed, infilled, and replaced with two smaller fixed windows. The primary elevation (northwest) has three metal pedestrian doors. There are four replacement sash windows on the second level, and two windows have been removed. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.



View showing the altered storefront, facing southeast (image courtesy of Google Streetview, 2013).

Resource No: 219

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1230 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.768874°/Longitude: -106.479952°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1960

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square, two-story commercial building has a flat roof and is constructed with brick.

The northwest and northeast elevations have a decorative brise soleil on the second level. The second level of the northeast elevation has aluminum sash windows. There is a wraparound metal awning that shelters the first-floor entrances and several large, fixed windows. The primary (northwest) elevation has four storefronts, each accessible by a metal door located behind metal gates. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 220

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1201, 1203, 1205 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.767958°/Longitude: -106.480461°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: This large, rectangular commercial building has a flat roof. It is constructed with

cinderblock and has a brick veneer on the primary (southeast) elevation. The primary elevation has four storefronts, each with a glass pedestrian door flanked by metal-frame

windows, or arched sash windows. There are three fabric awnings on one of the

storefronts. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing west.

Resource No: 221

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1207 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768077°/Longitude: -106.480318°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this building was limited due to fencing and its proximity to

adjacent buildings. This building has a flat roof and was originally constructed with adobe (according to Sanborn maps) but has been covered with stucco. The southeast elevation of the roofline is lined with rounded tiles. There is a small, shed roof covered with rounded metal tiles supported by wood brackets that shelters the primary metal pedestrian door. The visible sash windows have been replaced. The original front window opening appeared to be arched but has been modified to fit the replacement window. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Facing northwest.

Resource No: 222

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1209 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768131°/Longitude: -106.480248°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905


NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This historic-age portion of this building has a flat roof with a stepped parapet on the

northeast and southwest elevations. The building is constructed with brick and part of the building has been covered in stucco. There are visible arched window openings on the northeast elevation, but the windows have been removed or covered with plywood. There is a large ca. 1995 flat roof, stucco addition on the primary (southeast) elevation that blocks any additional view or assessment of the historic-age portion of this building. There is also ca. 2000 square cinderblock addition on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Red arrow indicates the historic-age portion of this resource, facing west.

Resource No: 223

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1225 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768420°/Longitude: -106.479795°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story, rectangular residence has a flat roof with a stucco, stepped parapet. The

building has an attached, wrap-around half-hip porch on the primary (southeast) elevation that is supported by wood spindles. The porch has a simple wood railing. The porch was modified to create additional living space on the northeast elevation. There is one wood pedestrian door and one window opening covered by plastic on the primary elevation. The windows on the southwest elevation have metal awnings, are replacements, and have been modified to fit an HVAC unit/window air conditioning units. This building has numerous additions on the northwest elevation that started in ca. 1990 and continued into the 2000s. There are several pre-manufactured sheds at the rear of this building. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends



Facing northwest.



Facing north.

Resource No: 224

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1227 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768470°/Longitude: -106.479706°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this resource was limited due to its proximity to adjacent buildings

and landscaping. This one-story duplex has a gable-on-hip roof and is clad in stucco. There is a full-width attached porch on the primary (southeast) elevation that is supported by wood posts and turned spindles, and there is a simple wood railing around the perimeter of the porch. There are two metal pedestrian doors on the primary elevation. All visible windows have been replaced, and several have been modified to fit both the original window opening and to accommodate window air conditioning units. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Facing west.

Resource No: 225

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1231 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768527°/Longitude: -106.479631°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian one-story brick building has a gable-on-hip roof with a prominent front-

gable ell. There is an attached, partial-width porch on the southeast elevation with turned-wood spindles posts that matches the wood trim around the perimeter of the porch. Beneath the porch are two metal pedestrian doors, and one non-historic-age casement window. There is a second pedestrian door on the northeast elevation that has a small, shed roof supported by wood spindles in the frieze and matching wood trim with railing. Most window openings are topped with brick header arches and non-historic-age

replacement windows. A review of aerial imagery indicates there is a ca. 1990 addition on the northeast elevation that is not congruent in architectural style or materials. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource



Red arrow indicates the ca. 1985 addition, facing west.

Resource No: 226

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 610 Brown St., El Paso, Texas 79902

Latitude: 31.768998°/Longitude: -106.479475°

Function/Sub-function: Domestic/Multiple Dwelling


Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building was historically a tenement house. This one-story, rectangular apartment

building has a flat roof and is constructed with brick. The roofline has a decorative brick frieze. Access to each apartment is available through a metal door on both the northwest and southeast elevations. The southwest and southeast elevations have stone lintels, replacement sash and fixed windows, and metal security bars over all windows and doors. There is a small addition on the northwest elevation, but its date of construction was not apparent from historic aerials. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing northeast.



Facing east (image courtesy of Google Earth, 2022).

Resource No: 227A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1306 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769231°/Longitude: -106.479424°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian house has a hipped roof with projecting front-gable roof. There are two

visible brick chimneys. The resource has decorative wood imbrication in the gable-end. This building is constructed with brick. A review of historic aerials indicates this building has a ca. 1950 attached porch on the primary (northwest) elevation supported by several wood posts. There is also a metal railing around the perimeter of the porch. The primary pedestrian door is not historic-age, and the entrance has been modified with board and batten siding. All visible windows are non-historic-age replacements. This building has a substantial ca. 1950 shed roof addition on the southeast elevation that is incongruent in building materials compared to the rest of the residence. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.

Facing southeast.



Red arrow indicates modified entrance, facing south.

Resource No: 227B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1306 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769083°/Longitude: -106.479291°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a shed roof and is clad in stucco. There is one metal pedestrian

door covered by a metal security door. The entrance is flanked by two replacement aluminum sash windows, which are covered with security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not



Facing north (image courtesy of Google Earth, 2022).

Resource No: 228A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1308 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769267°/Longitude: -106.479348°

Function/Sub-function: Domestic/Single Dwelling


Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian house has a front-gable roof with two half-hip dormers, one on the

northeast and one on the southwest elevation. There are decorative wood imbrication in the gable-end, as well as one large non-historic-age replacement sliding window. There are two visible brick chimneys on the southwest elevation. The building is constructed with brick, although the primary (northwest) elevation has been covered with stucco. There is an attached, shed roof porch supported by three decorative metal posts. The pedestrian door is wood and has a small transom light. All visible windows are non-historic-age replacements. A review of historic aerials indicates this building has a large ca. 1980 shed roof addition on the rear (southeast) elevation. This elevation was not visible at the time of field investigations. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing east.

Resource No: 228B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1308 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769120°/Longitude: - 106.479239°

Function/Sub-function: Domestic/Secondary Structure (garage)

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story cinderblock building has a flat roof, is clad in stucco, and has a double-bay

overhead door. The building was extended in ca. 1980 to presumably create additional storage space. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing northwest (image courtesy of Google Earth, 2022).

Resource No: 229

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1310 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769303°/Longitude: -106.479284°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This National Folk house has a hip roof with projecting front gable with decorative wood

imbrication and a covered window in the visible gable-end. The building is mainly clad in stucco. The primary (northwest) elevation has a ca. 1970 attached porch supported by three plain wood posts. There is a metal railing around the perimeter of the porch. The primary pedestrian door is not historic-age, and all visible windows have been replaced. There is a substantial ca. 1950 shed roof addition on the rear (southeast) elevation, as well as two non-historic-age sheds and a non-historic-age garage located at the rear of the

parcel. Given the numerous alterations, the building lacks integrity of design,

workmanship, and research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing southeast.

Resource No: 230

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1312 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769366°/Longitude: -106.479214°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This National Folk house has a hip roof with a projecting front gable with a half-circle vent

in the gable-end. The building has two visible stucco chimneys. The building is clad in stucco. There is an attached shed roof porch with decorative wood dentils on the primary (northwest) elevation supported by several plain columns. The pedestrian door is wood with a small fanlight. All visible windows are replacement aluminum sash windows. This building has a ca. 1960 shed to gable roof addition on the southeast elevation that is incongruent in building materials compared to the rest of the house. There is also a non-historic-age, premanufactured shed on the rear of the parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing south.

Resource No: 231

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1314 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769425°/Longitude: -106.479130°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this resource was limited due to fencing. This Folk Victorian house

has a hip roof with projecting front-gable ell, and one visible brick chimney. There are decorative wood imbrication in gable-end. The building was constructed with brick but has been covered with stucco and there is a decorative tile veneer on the primary (northwest) elevation. There is an integrated, partial-width porch on the primary elevation supported by two columns. There is also a shed roof extension of the porch to the northwest elevation that is supported by two metal posts. The primary pedestrian door is wood and has a small transom light. All visible windows have been replaced, and many of the original window openings have been modified. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east.



Facing south.

Resource No: 232

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1320 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769488°/Longitude: -106.478999°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This National Folk house has a hip roof and four brick chimneys. The building is

constructed with brick. This residence has an integrated, full-width porch supported by several classical columns. The porch also has a masonry knee wall around the perimeter. The primary (northwest) elevation has a wood pedestrian door with a transom light, and it is flanked by two replacement sash windows. All visible windows on the other elevations have been replaced. A review of historic aerials indicates that this residence has a ca. 1950 shed-roof addition on the southeast elevation that has horizontal wood siding and older, replacement windows compared to the rest of the residence. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast.



Facing southeast.

Resource No: 233A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1326 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769571°/Longitude: -106.478812°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large, rectangular apartment building has a flat roof. The building is constructed with

brick and has decorative brick insects on the parapet on the northwest elevation. All visible windows have lintels and are replacement sash windows. The apartments are accessible on both the southwest and northeast elevations. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.



Facing south.

Resource No: 233B

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1326 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769628°/Longitude: -106.478695°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large, rectangular apartment building has a flat roof. The building is constructed with

brick and has decorative brick insects on the parapet on the northwest elevation. All visible windows have lintels and are replacement sash windows. The apartments are accessible on both the southwest and northeast elevations. The doors on the northeast elevation are wood and located beneath a small, rounded tile overhang supported by wood brackets. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 234A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 608 Brown St., El Paso, Texas 79902

Latitude: 31.768831°/Longitude: -106.479339°

Function/Sub-function: Industry/Machine Shop (Currently, Vacant/Not in Use)

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: The building is a central-bay former machine shop that is clad in corrugated metal and

wood paneling. The raised, front-gable center roofline has a clearstory that provided additional light inside the building, although many of the windows are now covered or missing. There is a large bay door on the southwest elevation. This elevation also has a metal pedestrian door and steel casement windows. Steel casement windows are also visible on the southeast and northwest elevations. At the time of field investigations, many windowpanes were missing, and the resource did not appear to be in use. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing east.

Resource No: 234B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1301 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768701°/Longitude: -106.479225°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a flat roof with a stepped parapet on the southwest, southeast,

and northwest elevations. The building is constructed with brick. The southeast elevation has fixed windows, each covered with a metal grate and tarp. This elevation also has a one-bay overhead door near the corner of the northeast elevation. The primary entrance is on the southwest elevation. It has one metal pedestrian door, one window, and one single-bay overhead door. Some of the window and door openings appear to be partially enclosed. A review of Google Streetview imagery indicates that this resource was previously an auto shop, until it was converted to a gym in ca. 2015. Research did not reveal that the building is associated with important events or people identified in the

historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northeast.



Facing north.

Resource No: 235

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1309 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.768894°/Longitude: -106.479080°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a pyramidal roof with exposed brick chimney and wood

imbrication in the gable-end on the primary (southeast) elevation over the front door. The wood imbrication in the gable-end is the only indication that the house once had Folk Victorian detailing. The building is clad in stucco. The primary (southeast) elevation has an infilled porch, replacement wood pedestrian door, and replacement windows. All visible windows on the northeast elevation have been replaced and the original window openings have been modified to fit the replacements. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing west.

Resource No: 236

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1317 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769002°/Longitude: -106.478909°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This rectangular building has a flat roof. It is constructed with brick and covered with

stucco, and there is a brick veneer on the primary (southeast) elevation that wraps around each corner. The primary elevation has two long glass block windows, one fixed window, and one set of metal-frame double pedestrian doors covered by a metal gate. A review of Google Streetview imager indicates that all windows and garage doors on the southwest and northeast elevations were infilled in the early 2000s. This building is shown on the 1927 Sanborn map but has a mid-twentieth century appearance. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not



Facing northwest.

Resource No: 237A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1325 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769121°/Longitude: -106.478711°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This dwelling has a flat, stepped roof with stepped parapet on the northeast and

southwest elevations. The building is constructed with brick and has modest brick coping

at the roofline. There is a partial-width, attached porch on the primary (southeast) elevation supported by two square, brick columns. The primary pedestrian door is metal, and it is flanked by replacement sash windows. The windows on the southwest elevation are replacement sash windows, each covered by metal security bars with an apparent lintel and sill. A review of historic aerials indicates that this building has a ca. 1990 shed roof, stucco addition on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing north.

Resource No: 237B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1325 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769260°/Longitude: -106.478787°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This small, square dwelling building has a flat roof with stepped parapet on the northeast

and southwest elevations. The building is constructed with cinderblock. There appears to be one pedestrian door and a small window on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast (image courtesy of Google Earth, 2022).

Resource No: 238

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1327 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769186°/Longitude: -106.478607°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This small, square brick dwelling has a flat roof with brick coping at the roofline and

stepped parapet on the northeast and southwest elevations. It is void of any distinct architectural style. There is a partial-width, attached shed roof porch supported by two brick columns on the primary (southeast) elevation. The primary elevation has a

replacement metal pedestrian door flanked by two replacement sash windows. All other

visible windows have been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing north.

Resource No: 239

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 611 Newman St., El Paso, Texas 79902

Latitude: 31.769311°/Longitude: -106.478499°

Function/Sub-function: Health Care/Clinic

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square building has a flat roof and is constructed with cinderblock. There is a masonry

veneer on the lower portion of this resource. The primary (southeast) elevation has multiple infilled windows, and a raised metal pedestrian door. The northeast elevation has

replacement fixed windows, and three large picture windows that replaced single-bay overhead doors in ca. 2012. A review of historic aerials indicates there is a large, ca. 1965 addition on the northwest elevation. The addition is also constructed with cinderblock and has both infilled and replacement fixed windows. There is one metal pedestrian door and one large overhead door on the primary (northeast) elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing west.



Facing northwest.



View showing the ca. 1965 addition, facing south.

Resource No: 240

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1406 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769907°/Longitude: -106.478312°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource has a hip roof, and the building is constructed with brick. The front façade of

this resource has been significantly altered, as a ca. 2010 shed-roof front-addition on the primary (northwest) elevation added to and enclosed a historically partial-width porch. Lintels and sills were apparent on each window opening, and all windows have been replaced and covered with metal security bars. Several of the original window openings on the southwest elevation have been altered to fit the replacements. There is a large, ca. 2010 L-shaped addition on the rear (southeast) elevation of this resource. The addition has a shed roof, is clad in stucco, and connects to a non-historic-age garage. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast.

Resource No: 241

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1408 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.769974°/Longitude: -106.478203°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian building has a hip roof with a prominent front-gable ell, and

the resource is constructed with brick. A circular window is located in the gable end, and a set of French doors (with no entry porch) are located in the front-gable ell. The building has a sheltered entrance on the northeast elevation, and the porch roof a single wood post. Each elevation has several replacement sash windows, and many of the visible windows had apparent lintels and sills. A review of Google Streetview imagery indicates that a window adjacent to the pedestrian door replaced a historic-age pedestrian entrance. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 242

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1410 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770029°/Longitude: -106.478121°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story house with Neoclassical detailing has a hip roof with a half-hip dormer with

three small, covered windows centered on the primary (northwest) elevation. The resource is constructed with brick. The building has a full-width porch that features brackets under the eaves and lonic columns. The porch also has a decorative brick knee wall. The pedestrian entrance on the northwest elevation has a metal security door and a small transom light. The two windows that flank the front door are non-historic-age sash windows. Given the lattice attached to the porch, and this resource's proximity to other buildings, it could not be determined if the windows on the northeast and southwest elevations were historic-age or replacements. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 243

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1412 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770083°/Longitude: -106.478011°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Neoclassical residence has a hip roof with a half-hip dormer with three

small windows centered on the primary (northwest) elevation. The resource is constructed with brick. The building has a full-width porch that features brackets under the eaves and lonic columns. The porch also has a decorative brick knee wall. The pedestrian entrance on the northwest elevation has a metal security door and a small transom light. The two windows that flank the front door are non-historic-age sash windows. Given the lattice attached to the porch, and this resource's close proximity to other buildings, it could not be determined if the windows on the northeast and southwest elevations were historic-age or replacements, but lintels were apparent. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 244

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1414 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770145°/Longitude: -106.477917°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Neoclassical residence has a hip roof with a half-hip dormer with covered

windows centered on the primary (northwest) elevation. The resource is constructed with brick. The building has a full-width porch that features brackets under the eaves and lonic

columns. The porch also has a decorative brick knee wall. The primary pedestrian

entrance is a non-historic-age glass door. All visible windows have been replaced, and the original window openings have been partially infilled to accommodate the replacements. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southeast.



Facing east/southeast.

Resource No: 245

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1416 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770214°/Longitude: -106.477827°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a hipped roof with a centered half-hip dormer on the northwest

elevation. The resource is constructed with brick. The attached full-width porch has been infilled and is clad in stucco, altering the entrance to this residence. The infilled porch has a non-historic-age flanked by non-historic-age sliding windows with false shutters. The windows on the southwest and northeast elevations have been replaced, and the original window openings have been modified to fit those replacements. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not



Facing southeast.



Facing southeast.

Resource No: 246

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1418 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770294°/Longitude: -106.477752°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Neoclassical residence has a hip roof with a half-hip dormer with four vents

centered on the primary (northwest) elevation. The building is constructed with brick. There is a full-width integrated porch on the northwest elevation that is supported by simple replacement square posts. Brackets are located under the eaves of the front porch roof, and there is a decorative metal railing on the entire perimeter of the porch. The wood pedestrian door is not historic-age, nor are the sash windows that flank the door. Lintels are apparent above all visible doors and windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.



Facing southeast.

Resource No: 247

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1428 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770370°/Longitude: -106.477565°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square commercial building has a flat roof and is constructed with cinderblock and

brick. The front (northwest) elevation has multiple storefronts with large, replacement windows beneath a full-width flat metal awning. Each window is covered with metal security bars. The entrances are centered on the northwest elevation and each wood pedestrian door has a small transom light. One storefront has been infilled with plywood and a small set of ribbon windows. The southeastern elevation of this building has three single-bay overhead doors, and one metal pedestrian door. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.



Facing west (image courtesy of Google Earth, 2022).

Resource No: 248

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 600 Newman St., El Paso, Texas 79902

Latitude: 31.769653°/Longitude: -106.477954°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1980

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This multi-story commercial building has a flat roof and is clad in stucco paneling. There

are multiple, large, fixed windows on each elevation, as well as metal-frame glass pedestrian doors. A review of historic aerial imagery indicates that this building replaced several apartment buildings. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.

Resource No: 249

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1421 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769845°/Longitude: -106.477513°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian building has a cross-gable on pyramidal roof and the building

is constructed with brick. There is an attached, shed roof porch supported by brick and wood columns, and the porch includes a stucco knee wall. The porch has a decorative turned spindle frieze. The primary (southeast) elevation has two replacement pedestrian doors, and both transom lights have been covered. All visible windows have been replaced, and some of the original window openings have been modified. A review of historic aerials indicates that this area was historically residential and intermixed with scattered commercial properties, and now this is the only extant residence on this side of the block. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing northwest.

Resource No: 250

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1423 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.769999°/Longitude: -106.477396°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1980

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large commercial structure has a gable roof centered between two raised, square hip

roof additions. The building is clad in stucco and brick veneer. There is a sheltered entrance to each retail space, supported by square columns. Each elevation has several large, fixed windows. There are multiple metal-frame glass doors and a single-bay overhead door on the northeast elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing west.

Resource No: 251

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 604 Langtry St., El Paso, Texas 79902

Latitude: 31.770500°/Longitude: -106.477104°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1940

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a shallow-pitched hip roof and is clad in stucco. All windows on

the southwest and southeast elevations have been replaced. The resource is accessed through a wood pedestrian door on the southwest elevation. The original porch has been half infilled and half gated. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing north.

Resource No: 252

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1506 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770739°/Longitude: -106.477071°

Function/Sub-function: Domestic/Multiple Dwelling


Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story apartment building has a flat roof and is constructed with brick. A majority

of the apartments are accessed on the southwest elevation. Each unit has a metal pedestrian door located beneath a small front-gable overhang with brackets, and there are several replacement sash windows covered by metal security bars adjacent to the doors. The northwest elevation has an attached full-width porch with a front-gable roof supported by two square, brick columns. A knee wall is located on the perimeter of the porch. The northwest elevation has two pedestrian doors covered by a metal screen door, and there is one sash window. The transom lights above the pedestrian doors have been infilled. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southeast.



Facing southeast.

Resource No: 253

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1508 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770767°/Longitude: -106.477009°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: Photodocumentation of this resource was limited due to fencing and a large tarp covering

a majority of the primary façade. This one-story National Folk resource has a hip roof with one centered hip dormer on the northwest and southeast elevations, and a projecting front-gable porch. There are wood shingles in the visible gable-end of the porch. The building is constructed with brick, and some portions have been covered with stucco. The gable pediment on the primary (northwest) elevation is supported by two wood posts, and the entrance is entirely covered by a metal gate. The attached shed roof front porch was covered by a large tarp. There is a large non-historic-age shed located at the southeast portion of this parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 254A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1510 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770818°/Longitude: -106.476940°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story National Folk residence has a front-gable roof with three brick chimneys on

the northeast elevation. The building was constructed with brick but has been covered with stucco. The visible picture window on the primary (northwest) façade has been replaced and is topped with a fabric awning. The primary elevation has a gable pediment supported by two classical columns, and the small porch has a stucco-covered-brick knee wall with modest brick designs around the perimeter. The porch has been infilled with frosted glass and a non-historic-age wood door. Research did not reveal that the building is associated

with important events or people identified in the historic context, and it is not

architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 254B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1510 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770690°/Longitude: -106.476835°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large shed has a side-gable roof with plywood in the gable-end, and the building is

clad in stucco. There is one small sash window covered by a metal security bar on the northeast elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Facing west.

Resource No: 255

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1512 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770871°/Longitude: -106.476866°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905


NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story, National Folk residence has a front-gable roof with wood shingles and a

tripartite opening of window flanked by two vents in the gable-end. This building was constructed with brick but has been covered in stucco. The primary (northwest) elevation has a full-height, two-story attached porch with a shed roof that is supported by square wood posts on both stories. The second story has a wood railing around the perimeter and one pedestrian door that has been covered with plywood. The lower level has a masonry knee wall that has been covered with stucco. There is one metal pedestrian door with a small transom light, and one replacement sash window covered by a metal security screen. Many of the windows on the other elevations have been replaced and the original window openings modified to fit window air conditioning units. At the time of field investigations, panes were missing from the window in the gable-end. A review of historic aerials indicates there is a large, ca. 1970 two-story addition on the southeast elevation that has vinyl siding. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Facing southeast.



Red arrow indicates the ca. 1970 addition, facing south.

Resource No: 256

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1514 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770912°/Longitude: -106.476755°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a hip roof with a centered hip dormer on the front (northeast)

elevation. The building was constructed with brick but has been covered with stucco. There is a full-width integrated porch supported by four square columns with a knee wall around the perimeter of the porch. The off-center pedestrian door is not historic-age and has a transom and sidelights. All visible windows have been replaced. A review of Google Streetview imagery indicates that the porch was enclosed until 2015. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing east.

Resource No: 257

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1516 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.770976°/Longitude: -106.476668°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story modest Neoclassical brick duplex has a hip roof and three brick chimneys

on the northeastern elevation. There is one centered, hip dormer with three small, fixed windows on the northwest elevation. There is an integrated, full-width porch on the primary facade that is supported by four fluted square wood columns with plain capitals. The columns rest upon a masonry knee wall around the perimeter of the porch. There are two metal pedestrian doors on the northwest elevation, each flanked by one replacement sash window. The visible windows on the other elevations have also been replaced, and the original window openings have been modified to fit the non-historic-age replacements. The window openings have brick sills and stone lintels. Both transom lights on the primary elevation have been infilled with brick. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 258

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1518 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771036°/Longitude: -106.476583°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story modest Neoclassical brick building has a hip roof. There is an integrated,

full-width porch on the primary facade that is supported by four fluted square wood columns with plain capitals. The columns rest upon brick pedestals and metal railing around the perimeter of the porch. There is one metal pedestrian door on the northwest elevation, as well as one sash window covered by metal security bars. A review of the existing stone lintels on each elevation of this building indicate that doors and windows have been infilled or the original openings have been significantly modified to fit replacements. At the time of field investigations, one-third of the porch had been covered with plywood. A review of Google Streetview Imagery indicates that a centered dormer was removed in ca. 2020 when the roof was replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.



Facing south.

Resource No: 259

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1520 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771096°/Longitude: -106.476507°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this resource was limited due to security fencing and vegetation.

This one-story building has a hip roof with a centered hip dormer on the northwest elevation. The building was originally constructed with brick and has been covered with stucco. There is a full-width, integrated porch supported by four replacement square columns. There are full-height metal security bars around the perimeter of the porch. The primary elevation has one wood pedestrian door covered by a metal screen door, and two replacement aluminum sash windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing southeast.



Facing southeast.

Resource No: 260

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 611 N. Lee St., El Paso, Texas 79902

Latitude: 31.771092°/Longitude: -106.476191°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian brick house has a prominent front-gable roof with wood shingles in the

gable-end and a tripartite opening with a vent flanked by two fixed windows (one of the window's glass is missing). There is one exposed brick chimney. The building has an integrated, partial-width porch supported by plain wood columns. One metal pedestrian door is located within the porch, and the other pedestrian door had been covered with plywood. The house sits upon a substantial masonry wall foundation. At the time of field investigations, all windows had been covered with plywood except for one aluminum sash window on the porch. Given the state of deterioration and missing/covered materials, it is unclear whether this resource is still used as a dwelling. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.

Resource No: 261

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1501 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770278°/Longitude: -106.476939°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1965

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This rectangular commercial building has a flat roof with a raised, stucco parapet on the

southeast elevation. The resource is constructed with cinderblock. The entrance is located on the southeast elevation and is accessible by a metal-frame glass pedestrian door with fabric awning. The primary (southeast) elevation has several square fixed windows beneath fabric awnings, as does the southwest elevation that are also located beneath fabric awnings. At the time of field investigations, several windows and doors had been completely or partially infilled. Research did not reveal that the building is associated with

important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Facing west.

Resource No: 262

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1505 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770356°/Longitude: -106.476817°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a front-gable roof with wood shingles and a wood bracket in the

visible gable-end. There is one brick chimney on the southwest eave wall. The resource was originally constructed with brick but has been covered in stucco. The primary entrance (southeast elevation) has been significantly altered with the prominent original full-width front porch with shed roof being infilled. There is one metal pedestrian door on that elevation. All of the visible window openings have stone sills with all visible windows replaced and are covered with metal security bars. A review of aerial imagery indicates that this building has a large ca. 1960 gable addition on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Red arrow indicates the location of the infilled porch, facing north.

Resource No: 263A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1507 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770443°/Longitude: -106.476762°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story, side-gable house has a centered shed-roof dormer on the primary

(southeast) elevation. The gable ends have several knee brackets under the eaves. The dormer has wood shingles, wood knee brackets, and two small, fixed windows. There are four brick chimneys visible in the roofline. The building is constructed with brick, and portions have been covered with stucco. Many of the visible windows have been replaced, infilled, or covered with plywood. The primary elevation (southeast) has an integrated porch with brick columns and a knee wall with recessed rectangular panels. The porch's openings are now screened by metal bars and the front façade of the house is not visible. A review of historic aerials indicates that this building has a large ca. 1980 gable addition on the northwest elevation that is incongruent in materials and constructed as compared to the older portion of the residence. Research did not reveal that the building is

associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing northwest.

Resource No: 263B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1507 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770546°/Longitude: -106.476801°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This small shed has a gable roof and a combination of corrugated metal and plywood

siding. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing southeast.

Resource No: 264

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1511 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770477°/Longitude: -106.476635°

Function/Sub-function: Commerce/Business (Currently, Health Care/Clinic)

Construction Date: Ca. 1960

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story, rectangular building has a flat roof. The building is constructed with

cinderblock and is covered with metal panels and a brick veneer on the primary (southeast) elevation. The primary elevation has several large, non-historic-age fixed windows, and one glass pedestrian door flanked by two large, fixed windows. There are three fabric awnings on the primary elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.

Resource No: 265

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1515 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770617°/Longitude: -106.476498°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian building has a hip roof with a projecting front-gable ell. A

diamond-shaped vent is seen in the gable end. The building was originally constructed with brick and has been covered with stucco. All visible sash windows are non-historic-age replacements and are covered with metal security bars. The primary pedestrian entrance is on the southeast elevation and is a metal door with small transom light. There is a replacement attached shed-roof porch on the southeast elevation that is supported by metal poles. The shed roof extends beyond the roofline of the house to create a carport space. A review of historic aerials indicates that this building has a very large ca. 2000 addition on the northeast elevation that has completely altered the rear façade. The addition has a shed roof and is constructed with stucco and has multiple glass block windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing northwest.

Resource No: 266

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1517 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770620°/Longitude: -106.476371°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian building has a hip roof with a projecting front-gable ell, and it

has one visible brick chimney on the northeast elevation. The building was originally constructed with brick but has been covered with stucco. The primary pedestrian entrance is located beneath a shed roof porch that is supported by three plain columns atop a knee wall. The doors are replacement metal doors, and all visible windows are replacement sash windows covered by metal security bars. A review of historic aerials indicates that this building has a large ca. 2000 L-shaped, shed roof addition on the rear (northwest)

elevation. Research did not reveal that the building is associated with important events or

people identified in the historic context, and it is not architecturally significant. ICF



Facing northwest.



Red arrow indicates the ca. 2000 addition, facing northwest.

Resource No: 267

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1521 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770723°/Longitude: -106.476302°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian brick building has a hip roof with a projecting front-gable ell,

There is a partial-width shed roof on the primary (southeast) elevation supported by wood posts and non-historic-age metal brackets. The porch also has a metal railing around the perimeter of the porch. The wood pedestrian door has a small transom light and is covered by a metal security door. Each window has been replaced, and some of the original arched window openings have been modified to fit the replacements. Each window is also covered by metal security bars. There is a non-historic-age shed and carport located at the rear of this parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing northwest.

Resource No: 268

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1525 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770883°/Longitude: -106.476240°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a flat roof with a raised parapet on the southeast elevation. The

building is clad in stucco. There is a single-bay overhead door and one metal pedestrian door on the southeast elevation. That same elevation also has two large sash windows covered by metal security bars. There is a large, ca. 2000 flat roof, cinderblock addition on the northwest elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Red arrow marks the ca. 1980 addition, facing north.

Resource No: 269

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1531 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.770833°/Longitude: -106.476008°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: ca. 1910

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story National Folk resource has a hip roof with a centered hip dormer on the

southeast elevation. The window on the dormer has been covered. The building was originally constructed with brick and covered with stucco in 2020. There is a small integrated porch with two columns with plain capitals atop a knee wall. Until 2020, there were two pedestrian entrances on the porch, each with a transom light. Both transom lights and one of the doors have been infilled, and the remaining door is a non-historic-age replacement. All visible windows have been replaced, and some are covered by a

decorative metal security bar on the lower half of each window. There is a ca. 1970 shed roof addition that is also clad in stucco on the northwest elevation. It was not visible from the public ROW. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Facing west.

Resource No: 270

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1600 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771383°/Longitude: -106.476020°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This oldest portion of this resource has a hipped roof with a hipped dormer on the

northwest elevation that shows up on the 1908 Sanborn map. The building was originally a house constructed with brick but has been covered in stucco. There are two metal pedestrian doors on the southwest elevation of this building, and all visible windows are non-historic-age replacements. A review of historic aerials indicates there is a large ca. 1965 shed roof addition on the southwest elevation that has a one-bay garage door (and presumably functions as a garage or storage space). The primary (northwest) elevation has an extensive ca. 1980 addition that has been upgraded and continually modified through 2020. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Red arrow marks the original dwelling, facing east.



View showing the ca. 1965 garage addition, facing northeast.

Resource No: 271

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1606 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771479°/Longitude: -106.475943°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a hip roof with a gable-front projection and a repeating arch front porch.

covered in stucco. The primary (northwest) elevation has been significantly altered. The building historically had a porch located beneath a gable roof. Around 2010, a large, full-width, half-hipped porch has been added to the northwest elevation. The porch is supported by four brick square columns with arched openings. There is one replacement pedestrian door on the primary elevation, and all visible windows are replacement aluminum sash windows covered by metal security bars. The window in the gable-end has

The resource was constructed of concrete block (per 1908 Sanborn maps) and is currently

been covered. There is a full-width ca. 1970 shed roof addition on the rear (southeast) elevation that was added to extend the dwelling space. The rear addition includes a small partial-width porch. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Red arrow indicates ca. 1970 addition, facing south.

Resource No: 272A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1608 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771498°/Longitude: -106.475840°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a hip roof with a hip dormer centered on the primary (northwest)

elevation. The resource was constructed of concrete block (per 1908 Sanborn maps) and is currently covered in stucco. There is one glass pedestrian door accessible only by an ADA ramp on the primary elevation, and two replacement aluminum sash windows

covered by fixed metal security bars. This building has had significant alterations, including infilled windows and doors and an altered front façade and primary entrance. The building also has an entirely infilled porch (what was historically a full-width porch). Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast.

Resource No: 272B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1608 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771398°/Longitude: -106.475696°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1940

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a flat roof with a parapet on the northeast and southwest

elevations. The building is constructed with masonry and no windows or doors could be seen. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing north.

Resource No: 273

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1610 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771530°/Longitude: -106.475680°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a front-gable roof. There is vinyl siding, two sash windows, and gable

returns seen in the visible gable-end, and the building has three visible chimneys on the southwest elevation. The building is clad in stucco. On the primary (northwest) elevation is an attached, partial-width shed roof porch supported by a concrete wall and stucco half-height posts. The porch has been covered with lattice and metal security bars, obscuring the pedestrian entrance. All visible windows have been replaced. There is a large, non-historic-age shed that has been converted to a garage located at the rear of this parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing east.

Resource No: 274

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1612-1614 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771622°/Longitude: -106.475614°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This brick National Folk duplex has a hip roof with a half-hip dormer with vent that is

centered on the primary (northwest) elevation. There is an attached full-width porch on the primary elevation that is supported by replacement classical columns. There is a

replacement metal railing around the porch. This residence has two pedestrian entrances

on the primary elevation, and both are wood doors with a metal screen door. The door and window openings are accentuated with brick header sills. There are also two large, replacement sash windows on the primary elevation. There is a ca. 1970 shed roof addition on the southeast elevation that is incongruent in building materials with the rest of the building. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Red arrow indicates the shed roof addition, facing southeast.

Resource No: 275

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1616 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771655°/Longitude: -106.475498°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Folk Victorian house has a front-gable roof with wood dentils and wood shingles in the

visible gable-ends. The building was originally constructed with brick but has been covered with stucco. There is a full-width porch with a projecting front-gable roof and a small shed-


roof portion, supported by three square columns. There is a knee wall around the

perimeter of the porch. The primary pedestrian entrance is on the northwest elevation and has a wood door with metal screen door and small transom light. There is also a large window with a diamond-motif transom on the primary (northwest) elevation covered by a fixed metal security bar. The window openings appear to have header brick sills. The visible windows on the southwest elevation have been replaced. At the time of field investigations, one of the windows in the gable-end had been covered with plywood. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southeast.



Facing east.

Resource No: 276A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1620A Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771774°/Longitude: -106.475404°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905


NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource was partially obscured by another historic-age resource (see Resource No.

276B). This brick house has a complex hip roof with a projecting hip-on-gable projecting ell. The front-facing gable-end has wood shingles and two small vents flanked by two small, engaged wood pilasters. The front door has a transom and window openings have stone lintels and sills. The visible windows are replacement metal sash windows. The front porch has a replacement shed roof with modest supporting wood poles. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing southeast.



Facing south.



Facing south.

Resource No: 276B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1620B Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771774°/Longitude: -106.475404°

Function/Sub-function: Commerce/Business (Restaurant)

Construction Date: Ca. 1975

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This rectangular building has a flat roof and is clad in stucco with a painted stone veneer

on the northwestern elevation. This restaurant has a metal-framed glass pedestrian door and metal security door, as well as a replacement, large picture window on the primary elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing southeast.

Resource No: 277A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1624 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771816°/Longitude: -106.475270°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building has a gable-on-hip roof with a ca. 1950 shed roof addition on the northwest

elevation. There is a small, closed brick chimney on the northeast elevation. This resource has a combination of stucco, plywood, and brick veneer. The primary (northwest) façade has an attached shed-roof porch supported by two metal posts. There is one wood pedestrian door and a large non-historic-age bay window on the northwest elevation. A large brick chimney is visible on the ca. 1950 addition. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing southeast.

Resource No: 277B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1624 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771728°/Longitude: -106.475226°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story secondary structure has a gable roof, is clad in stucco, and may be used as

an additional house on the property. There are several small aluminum sash and sliding windows, as well as one replacement metal paneled pedestrian door on the southeast elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing north.

Resource No: 278

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1626 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.771939°/Longitude: -106.475218°


Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman duplex has a hip roof, and the resource is constructed with brick. There is a

full-width integrated porch on the primary elevation that is supported by two square brick columns, and there is a brick knee wall around the perimeter of the porch. The primary elevation (northwest) has two pedestrian metal doors flanked by large, non-historic-age picture windows. The other visible windows on the northeast and southwest elevations have been replaced. The window openings appear to have stone lintels and sills. A stone foundation skirt is visible around the perimeter of the house. Until 2020, this building had four exposed brick chimneys on each corner of this residence. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not



Facing southeast.

Resource No: 279

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1628 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772016°/Longitude: -106.475086°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This square building has a flat roof with a raised and stepped parapet that was added in

ca. 2015. A review of Google Streetview imagery indicates that this building is constructed with brick but was covered with stucco in ca. 2015. The building once had a full-width awning that was also removed in ca. 2015. The centered metal-frame glass pedestrian door is located behind a metal security gate. Streetview imagery shows that the primary (northwest) elevation has been modified, as the large picture windows that formerly flanked the entrance have been replaced by small, rectangular fixed windows in 2015. There is a large non-historic-age metal shed/carport located at the rear of this parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing east.

Resource No: 280

El Paso County, Texas Project Location:

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1601 Missouri Ave., El Paso, Texas 79902

Latitude: 31.771100°/Longitude: -106.475748°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1960

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: The historic-age portion of this building is rectangular with a flat roof and stucco siding. It

> has several small, fixed windows in the upper third of the southwest and southeast elevations. Access to this building is available through a single-bay garage door on the southwest elevation that has a large metal gate. There is a large ca. 2000 addition on the northwest elevation that occupies the remainder of the parcel. It has a half masonry wall that supports a shed roof and is generally open-air access for air flow through the building, which is currently used as an iron works. The office for this business is Resource No. 281. An advertisement in the March 5, 1961 El Paso Times notes that this building was constructed for an air conditioning supply company. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the


NRHP.



Red arrow indicates the ca. 2000 addition, facing east.



Facing northeast.



Facing west/northwest.

Resource No: 281

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1605 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771069°/Longitude: -106.475562°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource is the office for and is connected to Resource No. 280. It was partially

obscured by security fencing and vegetation from the adjacent property. This one-story building has a pyramidal roof, and the building is constructed with brick that has been covered with stucco. There is a partial-width, attached shed-roof porch on the primary (southeast) elevation that is supported by two brick, square columns. There is a square opening balustrade around the perimeter of the porch. The building has one metal pedestrian door and replacement sash windows that have been modified to accommodate window air conditioning units. This resource has a large, L-shaped ca. 1970 rear addition on the northwest elevation that has a flat roof and is covered with stucco. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Facing northwest.

Resource No: 282A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1625 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771498°/Longitude: -106.475003°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Folk Victorian building has a pyramidal roof with a projecting ell that has

imbrication and a small, fixed window in the gable-end. The building was historically constructed with brick but has been covered with stucco. All visible windows have been replaced, and the original arched window openings were modified to accommodate the replacements. The primary entrance is beneath a small, attached shed-roof porch supported by a square brick column on the southern elevation. There are two metal pedestrian doors accessible through the porch. The building has a large ca. 1980 addition on the rear that has a flat roof, stepped parapet, and is clad in stucco. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Arrow indicates the location of the ca. 1980 addition, facing north.

Resource No: 282B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1625 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771603°/Longitude: -106.475139°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a gable roof and is clad in corrugated metal. There appears to

be a set of single-bay hinged garage doors on the northwest elevation, and sash windows visible on the northeast elevation. This type of outbuilding is common in the area and in Texas. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF



Facing south.

Resource No: 283A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1627 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771524°/Longitude: -106.474894°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a hip roof with a centered hip dormer on the primary

(southeast) elevation. The building is constructed with brick. There is an inset partial-width porch supported by two wood posts. Half of the front porch was infilled with cinderblock, with the two historic-age square, brick support posts are still intact. The building has two pedestrian entrances accessible through the porch, and both are non-historic-age metal doors with a rectangular transom light. All windows are non-historic-age replacements, and the original window openings have been modified to accommodate the replacements. At the time of field investigations, many materials were missing. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the

NRHP.



Facing north.

Resource No: 283B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1627 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771694°/Longitude: -106.475056°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1940

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This small building has a flat roof and is constructed with wood, masonry, and stucco.

There are three small, fixed windows on the northwest elevation that are covered with metal security bars. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.



Facing southeast (image courtesy of Google Streetview, 2022).

Resource No: 284

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 601, 603, 605, 607, 609, 611, 613, 615, 617 N. Dallas Street, El Paso, Texas 79902

Latitude: 31.771675°/Longitude: -106.474809°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This large, rectangular building was historically tenement housing. It has a flat roof and is

constructed with brick, although portions of the brick have been covered with stucco. Each apartment entrance has a replacement pedestrian door with a metal screen door and a small rectangular transom light. Each unit also has at least one replacement sash window, some of which are covered by security screens. Lintels are apparent above each door and window. Research did not reveal that the building is associated with important events or

people identified in the historic context, and it is not architecturally significant.



Facing north.



Facing northwest.



Facing south.

Resource No: 285

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1700 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772212°/Longitude: -106.474813°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1965

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This L-shaped commercial building has a flat roof with raised parapet on the northwest

corner of the building. The current building is clad in stucco with punctuations of masonry veneer. It has several non-historic-age fixed and sash windows on each elevation. A review of Google Streetview imagery indicates that resource was two separate buildings in 2007, and in 2011 the buildings were combined with a false front and addition on the

southeastern elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing east.



Facing southeast.



View of the building(s) in 2007, facing southeast (image courtesy of Google Streetview, 2007).

Resource No: 286

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 600, 602, 604, 606, 608, 610, 612, 614, 616 N. Dallas Street, El Paso, Texas 79902

Latitude: 31.771837°/Longitude: -106.474472°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1905

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This building was shown as an apartment building on the 1908 Sanborn maps. This large,

elevation, and the building is constructed with brick. There is a full-width front porch on the southwest elevation with a roof that is supported by several small, square posts. Each unit's entry is accessed from the front porch. Each unit has a non-historic-age sash window, and many have been modified to fit window air-conditioning units. Each apartment entrance also has a wood or metal door covered by a metal storm door with a small rectangular transom light. The building has a ca. 2000 shed roof addition on the southeastern elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

rectangular building has a flat roof with stepped parapet with brick frieze on the southeast

significant.



Facing east.



Facing southeast.



Red arrow marks the ca. 2000 addition, facing northeast.



Facing north.

Resource No: 287

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1709 E. Missouri Ave., El Paso, Texas 79902

Latitude: 31.771983°/Longitude: -106.474276°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a front-gable roof with a vent in the gable end, and the house

has two exposed brick chimneys on the eave walls. The building was originally constructed in brick that has been covered with stucco. All windows have been replaced, and some of the original openings have been modified to fit the replacements. There is an integrated full-width porch on the primary (southeast) elevation that is supported by two square columns. The porch has an arched opening and a concrete knee wall around the perimeter of the porch. There is one metal pedestrian door on the primary elevation. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as



Facing northwest.



Facing west.

Resource No: 288

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1704-1706 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772310°/Longitude: -106.474653°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1915

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building has a simple hip roof with a small half-hipped dormer centered on

the primary (northwest) elevation. This residence was originally constructed with brick but has been coated with stucco. The building has a full-width integrated porch supported by five replacement metal posts. There are two metal pedestrian doors on the primary (northwest) elevation. Between the two doors are non-historic-age sliding windows with accentuated sills. Windows on the northeast elevation have also been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource

as not eligible for the NRHP.



Facing southeast.



Facing southwest.

Resource No: 289

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1710 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772335°/Longitude: -106.474552°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman house has a cross-gable roof with wood shingles and wood knee brackets

in the gable-ends. The building was originally constructed with brick but has been covered with stucco. There is one visible brick chimney on the southwest elevation. The primary elevation has an integrated full-width porch supported by replacement heavy square columns. There is a knee wall around the perimeter of the porch. The primary elevation has one replacement metal pedestrian door. All sash windows have been replaced. A review of historic aerials indicates that this building has a large ca. 1975 addition on the rear elevation that has been enclosed for additional dwelling space. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing southeast.



Red arrow indicates the ca. 1975 addition and enclosed porch, facing east/southeast.

Resource No: 290

Project Location: El Paso County, Texas

Project Name an CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1712 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772438°/Longitude: -106.474421°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Craftsman house has a front-gable roof and was originally constructed with

brick but has been covered with stucco. Historically there were two brick chimneys on the eave walls of this resource that were removed/closed in ca. 2020. The primary entrance is below a front-gable partial-width attached porch that is supported by two heavy, square columns. There is a centered metal pedestrian door. All windows are non-historic-age replacement sash windows that are covered with metal security bars. A review of historic aerials indicates that this building has a large ca. 2000 shed roof addition on the southeastern elevation, and there is a non-historic-age premanufactured garage on the parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing south.



Facing southeast.

Resource No: 291

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1716 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772525°/Longitude: -106.474327°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story resource has a side-gable roof and a centered shed dormer. The resource is

clad in a combination of brick, plywood, and tile. Windows on the northeast and southwest elevations appear to have been infilled but retain security bars. There is one visible non-historic-age pedestrian entrance on the primary (northwest) elevation. The resource had a full-width porch supported by four columns that has been infilled with non-historic-age plywood siding and fixed pane windows. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 292

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1724 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772579°/Longitude: -106.474232°

Function/Sub-function: Domestic/Single Dwelling (Currently, Social/Big Brothers Big Sisters)

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: The original resource constructed on this property has a side-gable roof and is obscured by

a large ca. 1950 non-residential addition on both the primary (northwest) and rear (southeast) elevations. Given this resource's location, and the architecture of the surrounding properties, it was likely a Bungalow residence. The ca. 1950 addition has a flat roof and is clad entirely in brick. There is one recessed primary entrance with a metal door beneath a metal shed porch cover. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Red arrow notes the original portion of this resource, facing southeast.



Aerial view of Resource No. 292 (image courtesy of Google Earth, 2022). The red arrows note the ca. 1950 additions.

Resource No: 293

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1726 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772628°/Longitude: -106.474128°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Bungalow has a complex roof (front gable roof at front portion of house, hipped roof

on rear portion, and cross gable projection on southwest elevation). The gable end on the primary (northwest) elevation has wood shingles, wood brackets, and wood dentils. The resource is constructed with brick. There is an integrated, partial-width tile porch supported by one brick column, and there is a decorative metal railing surrounding the porch. The primary pedestrian entrance is accessible by the porch. There are numerous replacement metal sash windows on each elevation, with security bars over some of the windows. The small window in the gable-end has been infilled and contains a non-historicage air conditioner. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing south.

Resource No: 294A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1728 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772697°/Longitude: -106.474035°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman bungalow has a complex roof with plywood siding, two fixed windows, wood

brackets, and wood dentils in the gable-end. This resource is clad in brick, and the brick has been painted and, in some locations, covered in stucco. The building has a full-width integrated porch supported by two square brick columns. The primary pedestrian entrance is off center, and many of the sash windows have been replaced. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing southeast.



Facing south.

Resource No: 294B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1728 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772547°/Longitude: -106.473887°

Function/Sub-function: Domestic/Secondary Structure

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story building is a small secondary dwelling (or guest house) connected to a garage. The resource has a flat roof and is constructed with brick and cinderblock. There is

one pedestrian entrance on the primary (southeast) elevation, and one metal sash window. The single-car garage appears to have a sliding metal door. There is one window covered with plywood and there appears to be an infilled pedestrian entrance. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource

as not eligible for the NRHP.



Red arrow notes an infilled entrance or window, facing northwest.



Facing north.

Resource No: 295A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1730 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772772°/Longitude: -106.473932°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This Craftsman bungalow has a side gable with a cross hip roof with wood shingles, wood

dentils and brackets, and three small four-pane windows in the gable ends. The resource is clad in brick. There is an integrated, full-width porch, a portion of which has been infilled, supported by three brick columns. There is one visible pedestrian entrance on the primary (northwest) elevation, and several wood sash windows on each elevation. A review of aerial imagery indicates that this was the only building on the parcel until ca. 1950, when two secondary domestic structures were added to the southeast portion of the parcel. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing southwest.



Red arrow notes an infilled window, facing east.

Resource No: 295B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1730 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772656°/Longitude: -106.473773°

Function/Sub-function: Domestic/Multiple Dwelling

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This resource has a flat roof with parapets on the primary (southeast) and rear elevations

and exposed rafters on the side elevations and is clad in stone. The primary (southeast) elevation has two pedestrian entrances, each beneath a small clay tile awning. There are several metal sash windows on each elevation with plaster lintels and sills. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as

not eligible for the NRHP.



Facing west.

Resource No: 295C

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1730 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772604°/Longitude: -106.473838°

Function/Sub-function: Domestic/Single Dwelling


Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: Photodocumentation of this resource was limited due to space constraints within the alley

and its relationship to 295B, and it is on the 1948 Sanborn map. This resource has a flat roof and is clad in stone. It has one small, fixed window and two wood sash windows covered by a security bar on the southeast elevation. Given the lack of a pedestrian entrance from the alley, this resource is only accessible from Wyoming Avenue, suggesting it is likely a small guest house. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally

significant. ICF recommends the resource as not eligible for the NRHP.



Facing northeast.



Aerial view of Resources Nos. 295A, 295B, and 295C (image courtesy of Google Earth, 2022).

Resource No: 296

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1721 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772978°/Longitude: -106.474431°

Function/Sub-function: Domestic/Single Dwelling (Currently, Commerce/Business)

Construction Date: Ca. 1930

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story resource has no apparent architectural style and has a metal hipped roof.

The resource is clad in stucco with veneer masonry adorning the corners and the foundation. There is a full-width porch with a shed roof supported by decorative metal columns and a railing. There is one pedestrian entrance on the primary (southeast) elevation and on the northeastern elevation. There are several fixed windows on each elevation with decorative security bars. A review of historic aerials indicates this resource has had numerous non-historic-age additions on the northeast elevation (presumably at the time the property was converted from a single dwelling to a commercial business in the early 2000s). Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant.

ICF recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing north.



Aerial view of Resource No. 296 with ca. 2000 additions, as noted by the red arrows (image courtesy of Google Earth, 2020).

Resource No: 297

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1729 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.773014°/Longitude: -106.474261°

Function/Sub-function: Domestic/Single Dwelling

Construction Date: Ca. 1920

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story Craftsman bungalow has a front-gable roof with wood singles and wood

brackets in the gable-end. The resource is clad in brick. The is an integrated, full-width front porch supported by two columns with a brick railing surrounding the porch. There is one pedestrian entrance and several metal sash windows with metal security bars. There is a non-historic-age shed-roof addition on the rear (northwest) elevation clad in corrugated metal siding with infilled windows. There are several non-historic-age sheds at the back of this property. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF

recommends the resource as not eligible for the NRHP.



Facing northwest.



Facing northwest.

Resource No: 298

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1801 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.773363°/Longitude: -106.473810°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This two-story rectangular building with no apparent architectural style has a flat roof with

stucco siding punctuated by several equidistant brick columns. This resource has several sets of four metal frame windows. There is one primary recessed entrance, centered on the southeastern elevation, with two pedestrian doors. There is an integrated, covered garage on the first floor of this resource with access on the southwestern elevation. A review of historic aerials indicates that this resource replaced several small homes. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends

the resource as not eligible for the NRHP.



Facing north.

Resource No: 299

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1800 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.772991°/Longitude: -106.473661°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1950

NRHP Eligibility: Not eligible under Criterion A, B, or C

Integrity/Comments: This one-story commercial resource was originally a gas station. It has limited extant

Moderne detailing in its decorative horizontal banding on the upper third of the resource on the northeast and southwest elevations. It has a flat roof and is covered in stucco. There are three integrated garage doors, and one pedestrian entrance on the northwest elevation. This resource has several fixed windows on each elevation, each covered with decorative security bars and beneath awnings covered with metal rounded tiles. Two doors have been infilled on the northeastern elevation, and the awning above the primary pedestrian entry is missing materials. A review of historic aerials indicates the gas pumps were historically on the northeast elevation, but are not visible on aerials imagery by ca. 1990. The gas pumps are no longer extant. The building does not have programmatic elements of a specific brand of gasoline. Research did not reveal that the building is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not eligible for the NRHP.



Note the decorative banding, facing southeast.



Red arrows note the location of infilled doors, facing west.

Resource No: 300A

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1817 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.773834°/Longitude: -106.473306°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: This asymmetrical resource is of no apparent type or style and has a flat roof. This

resource is currently a hospice facility. It has stucco siding and numerous metal sash windows on each elevation, several of which have metal security bars. There are multiple pedestrian entrances on the eastern elevation. This building is part of a larger medical complex, and the complex includes non-historic-age additions to historic-age resources. Centered in the complex is a small courtyard. Research did not reveal that the building, or larger complex, is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing north.



Overview of Resource Nos. 300A and 300B, facing northwest.

Resource No: 300B

Project Location: El Paso County, Texas

Project Name and CSJ: Downtown 10 (CSJ: 2121-02-166)

Address, Lat/Long: 1827 Wyoming Ave., El Paso, Texas 79902

Latitude: 31.773838°/Longitude: -106.472978°

Function/Sub-function: Commerce/Business

Construction Date: Ca. 1970

NRHP Eligibility: Not eligible under Criterion A, B, or C


Integrity/Comments: This rectangular resource is of no apparent type or style and is now used as a hospice

facility. Like the other buildings within the complex, it has a flat roof and is clad in stucco.

It has numerous fixed windows on each elevation, as well as multiple pedestrian

entrances. This building is part of a larger medical complex, and the complex includes non-historic-age additions to historic-age resources. Research did not reveal that the building, or larger complex, is associated with important events or people identified in the historic context, and it is not architecturally significant. ICF recommends the resource as not

eligible for the NRHP.



Facing north/northeast.