SH99 Grand Parkway Segments H, I1 and I2 Proposer RFQ Q&A Matrix No. 4 September 24, 2014

No.	Document	ment Section No. and Page No.	Category	Question	Response
* Any document changes (other than RID updates) described in TxDOT's responses will be made in an Addendum to the RFQ unless otherwise indicated. RID updates are provided as they become available.					
24.	RFQ	Part A, 5.1/pg A-18 and 5.3.1/pg A-21; Part B, 2 Organization, Volume 2		We have only been able to identify a limited number of maintenance firms that meet the requirements for Lead Maintenance Firm and are willing to price and provide the COMA services. The Lead Maintenance Firm requirement is potentially limiting competition for this project. Please consider removing the COMA requirement or revising the RFQ to eliminate this barrier at the RFQ stage which has been done by TxDOT in past RFQs, including the SH 360 Project.	The requirement to identify a Lead Maintenance Firm and a Maintenance Manager is removed from the RFQ process as reflected in Addendum #4.